

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9225T

AAD2203-108

*Not Notified**Recovery B4 paint**2336.53***SHD9225T**

JTDKB3FUX03079965

200303878K

TOYOTA

PRIUS

28/3/2022

SMJ7093D / AIG

17/5/2019

30 MAR 2022**PART****LIST**

| | | | |
|---|---|----|------------------------------|
| 1 | COVER, REAR BUMPER | \$ | <i>Bu</i> 442.60 ✓ |
| 1 | REINFORCEMENT SUB-ASSY, REAR BUMPER | \$ | <i>Bu</i> 332.70 ✓ |
| 1 | COVER, REAR BUMPER, LOWER | \$ | <i>Sn</i> 15.40 X |
| 1 | GUARD, REAR BUMPER, CENTER | \$ | <i>nd 1011</i> 576.30 ✓ |
| 1 | RETAINER, REAR BUMPER SIDE, LH | \$ | <i>Sn</i> 116.50 X |
| 1 | RETAINER, REAR BUMPER SIDE, RH | \$ | <i>Sn</i> 117.70 X |
| 1 | PANEL SUB-ASSY, BACK DOOR | \$ | <i>n</i> 1,147.80 X |
| 1 | GARNISH SUB-ASSY, BACK DOOR, OUTSIDE | \$ | <i>n</i> <i>scr</i> 925.60 X |
| 1 | WEATHERSTRIP, BACK DOOR | \$ | <i>Sn</i> 372.30 X |
| 1 | LENS & BODY, REAR COMBINATION LAMP, LH (UPPER) | \$ | <i>Sn</i> 443.30 X |
| 1 | LENS AND BODY, REAR LAMP, LH (LOWER) | \$ | <i>Sn</i> 502.00 X |
| 1 | LENS & BODY, REAR COMBINATION LAMP, RH (UPPER) | \$ | <i>Sn</i> 443.30 X |
| 1 | LENS AND BODY, REAR LAMP, RH (LOWER) | \$ | <i>Sn</i> 502.00 X |
| 1 | COVER, FLOOR UNDER, NO.1 LH | \$ | <i>Sn</i> 175.10 X |
| 1 | COVER, FLOOR UNDER, NO.2 RH | \$ | <i>Sn</i> 241.90 X |
| 1 | COVER, REAR FLOOR CTR | \$ | <i>Sn</i> 229.90 X |
| 1 | COVER, DECK TRIM, REAR | \$ | <i>Sn</i> 126.70 X |
| 1 | PANEL SUB-ASSY, BODY LOWER BACK | \$ | <i>n</i> 650.30 X |
| 1 | REAR TAILGATE TOYOTA LOGO | \$ | <i>n</i> 47.90 ✓ |
| 1 | REAR TAILGATE WORDING 'PRIUS' | \$ | <i>n</i> 54.60 ✓ |
| 1 | REAR TAILGATE WORDING 'HYBRID' | \$ | <i>n</i> 54.60 ✓ |

| | | |
|--------------|-----------|-----------------|
| TOTAL | \$ | 7,518.50 |
| 25% | \$ | 1,879.63 |
| | \$ | 5,638.88 |

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9225T

AAD2203-108

Special Nett

| | | | | |
|-------------------------------------|-----------|------|-----------------|-------|
| 1SET PARKING AID | \$ | Shan | 700.00 | 220sn |
| 1SET REAR BUMPER CLIP | \$ | nn | 95.00 | 60sn |
| 2 WINDSCREEN SEALANT | \$ | nn | 150.00 | X |
| 1 WINDSCREEN MOULDING | \$ | nn | 200.00 | X |
| 1 WINDSCREEN INNER SPONGE SEAL | \$ | nn | 130.00 | X |
| 1 REAR TAILGATE STICKER "Trans-Cab" | \$ | nn | 80.00 | 30sn |
| 1 REAR TAILGATE STICKER "6555-3333" | \$ | nn | 80.00 | 30sn |
| 1 REAR BUMPER PROTECTOR | \$ | nn | 180.00 | X |
| 2 SEAM SEALANT | \$ | nn | 250.00 | X |
| 1SET REAR BUMPER RETAINER CLIP | \$ | nn | 85.00 | X |
| 1 REAR NUMBER PLATE WITH HOLDER | \$ | nn | 140.00 | X |
| 1SET TAILLAMP LOWER CLIP | \$ | nn | 55.00 | X |
| 1SET TAILLAMP UPPER CLIP | \$ | nn | 55.00 | X |
| 1 END PANEL TRIM CLIP | \$ | nn | 65.00 | X |
| 1 REAR BUMPER ADVERTISEMENT | \$ | nn | 100.00 | 60sn |
| TOTAL | \$ | | 2,365.00 | |
| TOTAL PARTS | \$ | | 8,003.88 | |

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.

\$ nn 300.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ nn 380.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 1,750.00 300l

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ nn 380.00 X

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$ nn 180.00 X

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9225T

| | | |
|---|----|---------------------------|
| To Rust-Proofing and apply undercoat Of The Affected Areas. | \$ | <i>nn</i> 250.00 <i>X</i> |
| Putty And Spray Painting Of The Affected Portion. | \$ | 1,750.00 <i>4401</i> |
| To reinstall rear bumper parking sensor. | \$ | 170.00 <i>501</i> |
| To Check Electrical Lighting Concerned. | \$ | 170.00 <i>151</i> |
| To transfer of luggage floor panel fittings, attachment and perform water seepage test. | \$ | <i>nn</i> 380.00 <i>X</i> |

TOTAL \$ 5,710.00
Over All Total \$ 13,713.88
(PART-BY-PART) Repair Days
~~7~~ **DAYS**
2 1/2 days
LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: