



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE)SINGAPORE 417883 ON BEHALF OF YEE MUN LEONG			Ref: CS/TP22002978/Uvy3e2 Date: 11/04/2022 Code: TP149	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	Veh. Inspected	SLH 5591T	
	Policy No.	Coverage (\$)	0.00	
	Claim No.	Excess (\$)	0.00	
	Assign From	Assign Date	31/03/2022	
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ C180K (A)	c.c	1796
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	WDD2040462A214549	Colour	WHITE
	Odometer	208812 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/40Z R18	TOURADOR	5 mm
	L/H Front Tyre	225/40Z R18	X SPEED	5 mm
	R/H Rear Tyre	245/40 R18	PIRELLI	6 mm
	L/H Rear Tyre	245/40 R18	PIRELLI	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	29/03/2022	Inspection Date	31/03/2022
	Survey held at	BLUWEL AUTOMOTIVE SERVICE PL BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	