

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

SURIYATI BTE SAMURI
BLK 104 BUKIT BATOK CENTRAL #03-275
SINGAPORE 650104

Contact : 96381524, 96630599

TP SMRT.
Veron

TAX INVOICE

Repair Code : CLM15490

Date in : 30/03/2022

Vehicle Num. : SJL1030A

Model : TOYOTA ALLION 1.5 A

Chassis/Eng# : NZT2603036232/1NZZD267029

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BOOTLID <i>Dented</i>	1	881.70	✓ 881.70
REAR BOOTLID 'LOGO' EMBLEM <i>Ken</i>	1	68.40	✓ 68.40
REAR BOOTLID CHROME MOULDING HANDLE <i>Ken</i>	1	231.55	+ 231.55
REAR BOOTLID HINGES L/R <i>Ken</i>	2	182.25	+ 364.50
REAR BOOTLID INNER RUBBER SIDE GUIDE STOPPER L/R <i>Ken</i>	2	18.70	+ 37.40
REAR BOOTLID INNER TRIM <i>Ken 785</i>	1	581.10	+ 581.10
REAR BOOTLID MECHANISM LOCK <i>Dented</i>	1	387.25	✓ 387.25
REAR BOOTLID WEATHER STRIP <i>Cut</i>	1	281.10	✓ 281.10
REAR BUMPER <i>Dehnd.</i>	1	1217.80	✓ 1,217.80
REAR BUMPER BRACKET L/R <i>Ken RT Dented.</i>	2	55.00	110.00 55
REAR BUMPER SIDE RETAINER L/R <i>Ken</i>	2	76.40	✓ 152.80
REAR END PANEL <i>Dented</i>	1	781.90	✓ 781.90
REAR END PANEL ANTENNA SENSOR <i>Cut</i>	1	211.70	✓ 211.70
REAR END PANEL INNER TOP GARNISH <i>Dehnd</i>	1	281.50	✓ 281.50
REAR FENDER INNER TRIM L/R <i>RT Dehnd</i>	2	537.80	1,075.60 537.80
REAR SPARE TYRE INNER TOP BOARD COVER <i>Ken</i>	1	267.00	X. 267.00
REAR TAILLAMP INNER BLACK GASKET L/R <i>Ken</i>	2	25.00	✓ 50.00
REAR TAILLAMP L/R <i>Cut</i>	2	488.60	✓ 977.20

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
? Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

SURIYATI BTE SAMURI
BLK 104 BUKIT BATOK CENTRAL #03-275
SINGAPORE 650104

Contact : 96381524, 96630599

TAX INVOICE

Repair Code : CLM15490

Date in : 30/03/2022

Vehicle Num. : SJL1030A

Model : TOYOTA ALLION 1.5 A

Chassis/Eng# : NZT2603036232/1NZD267029

REAR TAILLAMP LOWER BRACKET L/R	2	161.40	322.80
Subtotal before discount			8,281.30
Percentage discount	25%		2,070.33
Sub-total 1			6,210.98
REAR BOOTLID INNER SOUND PROOF	1	250.00	250.00
REAR BOOTLID INNER TRIM GARNISH CLIPS - SET	1	50.00	50.00
REAR BUMPER CLIPS - SET	1	50.00	50.00
REAR BUMPER REFLECTOR - SET	1	250.00	250.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	30.00	30.00
REAR FENDER INNER TRIM CLIPS L/R - SET	2	50.00	100.00
REAR TAILLAMP CLIPS L/R - SET	2	25.00	50.00
Subtotal before discount			780.00
Percentage discount	0%		0.00
Sub-total 2			780.00
Parts-total			6,990.98

LABOUR

To Transfer Rear Bootlid Mechanism Lock Outer Handle Reflector

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

~~80.00~~
~~80.00~~
~~100.00~~

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

SURIYATI BTE SAMURI
BLK 104 BUKIT BATOK CENTRAL #03-275
SINGAPORE 650104

Contact : 96381524, 96630599

TAX INVOICE

Repair Code : CLM15490

Date in : 30/03/2022

Vehicle Num. : SJL1030A

Model : TOYOTA ALLION 1.5 A

Chassis/Eng# : NZT2603036232/1NZD267029

To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

2,580.00

Parts & Labour Total

9,570.98

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adm L
1/s 31/03/22
06 Days.

Total: 6739.61
L/S S.HK

S.4K.