

# EDWIN GARAGE AIRCON & REPAIR

BLK 5032 Ang Mo Kio, Industrial Park 2 . #01-295, Singapore 569535

Tel: 97856612

Not Authash

Repair After Paint

JTEK B3G14

10 days

Vehicle No: SLS1991R  
Model : TOYOTA/HARRIER TURBO

| PARTS                                      | QTY | AMOUNT       |   |
|--|-----|--------------|---|
| REAR BUMPER 904                            | 1   | \$ 1,089.00  | ✓ |
| REAR BUMPER LOWER                          | 1   | \$ 466.00    | ✓ |
| REAR BUMPER SIDE BRACKET LH/RH@82.70       | 2   | \$ 165.40    | X |
| REAR BUMPER REFLECTOR LH/RH@58.60          | 2   | \$ 116.40    | X |
| REAR BUMPER FOAM                           | 1   | \$ 122.60    | ✓ |
| REAR REVERSE SENSOR@481.90 ✓               | 2   | \$ 1,927.60  | ✓ |
| REAR END PANEL 782                         | 1   | \$ 831.60    | ✓ |
| REAR END PANEL INNER GARNISH               | 1   | \$ 359.40    | ✓ |
| REAR END PANEL ANTENNA SENSOR              | 1   | \$ 165.70    | ✓ |
| REAR FLOOR PANEL                           | 1   | \$ 954.00    | ✓ |
| REAR FLOOR PANEL TOP BOARD                 | 1   | \$ 820.40    | X |
| REAR FLOOR PANEL TOP UTILITY TRAY          | 1   | \$ 458.20    | X |
| REAR FLOOR PANEL TRAY LH                   | 1   | \$ 328.40    | X |
| REAR FLOOR PANEL TRAY RH                   | 1   | \$ 502.50    | X |
| REAR FENDER INNER TRIMBOARD LH/RH@585.40   | 2   | \$ 1,171.20  | X |
| REAR TAILGATE 1718                         | 1   | \$ 2,378.00  | ✓ |
| REAR TAILGATE 'LOGO' EMBLEM                | 1   | \$ 57.30     | X |
| REAR TAILGATE 'HARRIER' EMBLEM             | 1   | \$ 73.70     | ✓ |
| REAR TAILGATE 'TURBO' EMBLEM               | 1   | \$ 78.90     | ✓ |
| REAR TAILGATE INNER TRIMBOARD              | 1   | \$ 515.00    | X |
| REAR TAILGATE LOCK 423                     | 1   | \$ 974.00    | ✓ |
| REAR TAILGATE AUTO DAMPER LH/RH@780        | 2   | \$ 1,560.00  | X |
| REAR TAILGATE WEATHERSTRIP                 | 1   | \$ 442.00    | X |
| REAR TAILGATE WINDSCREEN MOULDING LOWER    | 1   | \$ 62.50     | ✓ |
| REAR TAILGATE WINDSCREEN MOULDING LH/RH@50 | 2   | \$ 100.00    | ✓ |
| FRONT BUMPER 811-20                        | 1   | \$ 1,436.60  | ✓ |
| FRONT BUMPER LOWER LIP                     | 1   | \$ 340.20    | X |
| FRONT BUMPER LOWER GRILLE                  | 1   | \$ 443.10    | X |
| FRONT BUMPER FOG LAMP LH                   | 1   | \$ 516.00    | X |
| FRONT BUMPER FOG LAMP COVER LH             | 1   | \$ 122.10    | X |
| FRONT BUMPER SIDE SPONGE LH@49.8           | 1   | \$ 49.80     | X |
| FRONT BUMPER SIDE BRACKET LH/RH@117.40     | 2   | \$ 234.80    | X |
| FRONT BUMPER TOW COVER                     | 1   | \$ 38.90     | ✓ |
| HEADLAMP LH 6714.50                        | 1   | \$ 6,714.50  | ✓ |
| HEADLAMP LOWER BRACKET LH                  | 1   | \$ 41.80     | X |
|  |     | \$ 25,657.60 |   |
| Less 25%                                   |     | \$ 6,414.40  |   |
| Sub Total                                  |     | \$ 19,243.20 |   |
| Balance                                    |     | \$ 19,243.20 |   |

## S/NETT ITEMS

|  |       |           |        |
|--|-------|-----------|--------|
| REAR NUMBER PLATE                      | 1     | \$ 50.00  | X      |
| REAR BUMPER CLIP                       | 1 SET | \$ 60.00  | ✓      |
| REAR END PANEL INNER GARNISH CLIP      | 1 SET | \$ 50.00  | ✓      |
| REAR FENDER INNER TRIMBOARD CLIP LH/RH | 2 SET | \$ 120.00 | X      |
| REAR FLOOR PANEL INSULATION MAT        | 1     | \$ 300.00 | 120.00 |
| REAR TAILGATE INNER TRIMBOARD CLIP     | 1 SET | \$ 80.00  | X      |
| REAR WINDSCREEN GLASS SEALANT          | 2     | \$ 100.00 | 40.00  |
| FRONT NUMBER PLATE                     | 1     | \$ 50.00  | 45.00  |

FRONT BUMPER CLIP  
PANEL JOINT SEALANT

|       |    |          |
|-------|----|----------|
| 1 SET | \$ | 60.00    |
| 4     | \$ | 240.00   |
|       | \$ | 1,110.00 |

NEC

60.00  
240.00  
1,110.00

Balance

\$ 20,353.20

**LABOUR**

CHECK REAR WIRING AND LIGHTING SYSTEM  
REMOVE/REPLACE/REFIT REAR UPHOLSTERY ETC  
REMOVE/REPLACE/REFIT REAR WINDSCREEN GLASS  
REMOVE/REPLACE/REFIT TAILGATE COMPONENTS, ROOF SPOILER ETC  
REMOVE/REPLACE/REFIT REAR REVERSE SENSOR  
PANEL BEATING ON REAR AFFECTED AREAS  
SPRAY PAINTING ON REAR AFFECTED AREAS  
CHECK FRONT WIRING AND LIGHTING SYSTEM  
PANEL BEATING ON FRONT AFFECTED AREAS  
SPRAY PAINTING ON FRONT AFFECTED AREAS  
PERFORM SYSTEM DIAGNOSTIC & RESET ECU  
APPLY ANTI RUST ON AFFECTED AREAS

|    |          |       |
|----|----------|-------|
| \$ | 100.00   | 201   |
| \$ | 200.00   | 1201  |
| \$ | 200.00   | 1201  |
| \$ | 100.00   | 601   |
| \$ | 100.00   | 601   |
| \$ | 1,500.00 | 12001 |
| \$ | 1,200.00 | 10001 |
| \$ | 100.00   | 201   |
| \$ | 400.00   | 2001  |
| \$ | 400.00   | 2001  |
| \$ | 300.00   | x     |
| \$ | 150.00   | 901   |
| \$ | 4,750.00 |       |

Grand Total

\$ 25,103.20

**LKK Auto Consultants hence notify  
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: