

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22002993/VQY3E2**Date:** 21/10/2022**REFERENCE**Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00229662100

**Claimant Vehicle  
No :** SLU9017R**Insured Vehicle  
No :** SFY18Y

Date of Loss: 27/03/2022

Nature of Claim: TP

Claim  
No: SNM22D202177/C02/IRENE**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SLU9017R**

Make &amp; Model: HONDA VEZEL, 1.5 (A)

Engine No: LEB5963930

Reg. Date: 18/12/2017 (Man. Year: 2017)

Chassis No: RU31263910

Colour: Black

Odometer: 62108 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

**CONDITION OF TYRES**

Front Tyre Size: 215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side: Dunlop 5 mm

Rear Left Side:

Dunlop 5 mm

Front Right Side: Dunlop 5 mm

Rear Right Side:

Dunlop 5 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>         | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                         | 5,402.00          | 2,130.00          | 3,272.00          | 60.57         |
| Miscellaneous Items           | 0.00              | 0.00              | 0.00              |               |
| Labour                        | 4,650.00          | 1,160.00          | 3,490.00          | 75.05         |
| Paintwork Labour              | 0.00              | 0.00              | 0.00              |               |
| Towing                        | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (S\$)</b>      | <b>10,052.00</b>  | <b>3,290.00</b>   | <b>6,762.00</b>   | <b>67.27</b>  |
| <b>+ GST 7.00/7.00% (S\$)</b> | 703.64            | 230.30            | 473.34            | 67.27         |
| <b>Nett Amount (S\$)</b>      | <b>10,755.64</b>  | <b>3,520.30</b>   | <b>7,235.34</b>   | <b>67.27</b>  |

**INSPECTION**

Date of Assignment: 19/10/2022

Date Inspected: 01/04/2022

Estimated Period of Repair: 4.0 days

Inspected At:

Jack Cars Enterprise Pte Ltd  
BLK3007 UBI ROAD 1 #01-450  
Singapore 408700**Adjuster:** Thevan Thomas Karthikesavan**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS \$2,724.00 NETT)

REPAIR DETAILS

|               |                                                                                                                                                                              |                                                       |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------|
| Reference     |                                                                                                                                                                              |                                                       |
| Part Source:  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 21 Oct 2022)         |
| Parts:        | M1-SUV                                                                                                                                                                       | HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour:       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                     |
| Print Code:   | (Unsubmitted, no print-code for SLU9017R)                                                                                                                                    |                                                       |
| Validity:     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                       |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                       |

Recommended Parts

| No. | Qty | Part No. | Particulars               | Condition   | Repairer's  | Amount       |
|-----|-----|----------|---------------------------|-------------|-------------|--------------|
| 1   | 1   |          | *REAR BOOT                | Dented      | 1,200.00 FL | *1,200.00 FL |
| 2   | 1   |          | *REAR BOOT GARNISH        | Serviceable | 350.00 FL   | *- FL        |
| 3   | 1   |          | *REAR BOOT WEATHERSTRIP   | * Check     | 280.00 FL   | *- FL        |
| 4   | 1   |          | *REAR BUMPER              | Dented      | 900.00 FL   | *900.00 FL   |
| 5   | 1   |          | *UNDERCARRIAGE COVER      | * Check     | 420.00 FL   | *- FL        |
| 6   | 1   |          | *REAR END PANEL           | * Check     | 780.00 FL   | *- FL        |
| 7   | 1   |          | *REAR END PANEL TOP COVER | * Check     | 150.00 FL   | *- FL        |
| 8   | 1   |          | *SIDE PAD - LEFT          | Repair      | 510.00 FL   | *- FL        |
| 9   | 1   |          | *TAIL LAMP - INNER LEFT   | * Check     | 580.00 FL   | *- FL        |
| 10  | 1   |          | *TAIL LAMP - OUTER LEFT   | * Check     | 720.00 FL   | *- FL        |
| 11  | 1   |          | *CLIPS, RIVETS & SCREWS   | Necessary   | 100.00 FS   | *30.00 FS    |
| 12  | 1   |          | *REVERSE SENSOR           | Cut         | 220.00 FS   | *200.00 FS   |
| 13  | 1   |          | *VEZEL EMBLEM             | Necessary   | 95.00 FS    | *95.00 FS    |
| 14  | 1   |          | *HYBRID EMBLEM            | Necessary   | 75.00 FS    | *75.00 FS    |
| 15  | 1   |          | *WINDSCREEN SEALANT       | Necessary   | 100.00 FS   | *50.00 FS    |
| 16  | 1   |          | *REAR END PANEL SEALANT   | * Check     | 100.00 FS   | *- FS        |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                    |          |          |
|----------------------------------------------------|----------|----------|
| Sub Total (S\$)                                    | 6,580.00 | 2,550.00 |
| - List Item Discount on L Items 20.00/20.00% (S\$) | 1,178.00 | 420.00   |
| Total Parts (S\$)                                  | 5,402.00 | 2,130.00 |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                                                                    | Lab.Type | Repairer's      | Amount          |
|---------------------------------|--------------------------------------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                                                                                                                |          |                 |                 |
| 1                               | TO PUTTY & SPRAY PAINT OF AFFECTED AREA                                                                                        | New      | 1,800.00        | 400.00          |
| 2                               | TO PANEL BEAT & TO REMOVE DAMAGED & NECESSARY PARTS & ATTACHEMENTS; KNOCK, JACK, WELD, RESHAPE AND ALIGN ALL AFFECTED PORTIONS | New      | 1,500.00        | 500.00          |
| 3                               | TO CHECK LIGHTING SYSTEM, WIRING & REWIRE                                                                                      | New      | 250.00          | 40.00           |
| 4                               | TO REMOVE AND REINSTALL TAILGATE COMPONENTS                                                                                    | New      | 220.00          | 40.00           |
| 5                               | TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY<br>(* Check)                                                                      | New      | 280.00          | 0.00            |
| 6                               | TO REMOVE & REINSTALL SENSORS                                                                                                  | New      | 200.00          | 30.00           |
| 7                               | TO REMOVE & REINSTALL REAR WINDSCREEN                                                                                          | New      | 200.00          | 120.00          |
| 8                               | ANTI RUST TREATMENT                                                                                                            | New      | 200.00          | 30.00           |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                                                                |          | <b>4,650.00</b> | <b>1,160.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >