

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# : CB7045D

Accident Date : 31/3/2022

Location : KJE TOWARDS PIE

Model:

ISUZU/LT134P

14/12/2012

3P:

GY3483E (AIG)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Rear bumper <i>Dehnd.</i>	2,600.00	1500.00 (SN)	
2	1pc	Rear bumper lower diffuser <i>Amld.</i>	910.20	400.00 (SN)	
3	1pc	Rear bumper enforcement <i>new</i>	1,600.00	X.	
4	1pc	Rear engine cover <i>Rear</i>	2,400.00	X.	
5	1pc	Rear engine cover hinges <i>new</i>	600.00	X.	
6	1pc	Rear engine cover lock <i>new</i>	455.30	X.	
7	1pc	Rear o/s tail lamp <i>cut.</i>	955.80	500.00 (SN)	
8	1pc	Rear 60km <i>new</i>		20.00	10.
9	1pc	Rear biz safe 3 sticker <i>new</i>		80.00	50
		<i>S-N: 2460</i>	Sub-Total:	9,521.10	100.00
			15%	0%	10%
			After Less %:	8,092.94	100.00
		Labour			
1		To dismantle damaged parts, straighten & welding.	2,000.00	500	
2		To spray painting.	1,400.00	600	
4		To remove and replace rear tail-gate (Mechanism).	200.00	X.	
10		To check wiring.	100.00	30	
11		To re-seal anti-rust. <i>1170</i>	100.00	40	
			Sub-Total:	3,800.00	
			Total:	11,992.94	
			After Less 20%:	9,594.35	

Chan San Choon
Director
DipEng, AAE MIMI, MSAE(Aust)



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a 'Without Prejudice' basis
- No illegal modifications is allowed 24 hr accident call
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Mobil 1



PAYNOW

Adrian Lg
L/S 31/03/22.
04 Days.
total: 3630
L/S: 2-91K