



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0254/2022/JT
DATE : 30-Mar-22
WIP : 17811

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 31/3/22

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS LIM HUI FANG IRA
ADDRESS : 41 HUME AVENUE
#09-02
SINGAPORE 598738
TELEPHONE : HP +65 98770808
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1700090242-04
VEHICLE NO : **SJY 8869 H**
MODEL CODE : AUDI A3 SEDAN 1.4 TFSI 8V
MODEL YEAR : 16/12/2017
ENGINE NO : CHZ 575944
CHASSIS NO : WAUZZZ8V7J1022748
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 29-Mar-22
PLACE OF ACCIDENT : OPPOSITE CONCORDE HOTEL

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJY 8869 H

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID.	S/N \$ 280.00 /	
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$ 280.00 /	
3	TO RENEW REAR WINDSCREEN AND RHS 1/4 GLASS TO FACILITATE THE RENEWAL OF LHS REAR FENDER.	S/N \$ 600.00 /	
4	TO INSTALL SOLAR FILM FOR AFFECTED GLASSES.	S/N \$ 400.00 /	
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN AND LHS 1/4 GLASS.	S/N \$ 200.00	150
6	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$ 1,400.00 /	(photo)
SUB TOTAL LABOUR CHARGES		: \$ 3,160.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJY 8869 H

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$ 1,400.00	(photo)
8	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND WELD RHS REAR FENDER, RHS BOTTOM - 1 PLATE, RHS D-PILLAR REINFORCEMENT AND RHS WHEEL HOUSING OUTER. TO REPAIR SPARE WHEEL HOUSING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. <i>end part - 3</i>	\$ 9,100.00 <i>10 4/1</i>	5000
9	TO RESPRAY REAR BUMPER, REAR LID, RHS REAR FENDER, FUEL CAP, RHS D-PILLAR REINFORCEMENT, RHS SILL * PANEL, ROOF CHANNEL, DRAIN CHANNEL, DOOR * ENTRANCE SPARE WHEEL HOUSING AND REAR END PANELLING.	\$ 7,000.00 <i>6-5 x 550</i>	3575
10	TO CARRY OUT FIRST MEASUREMENT ON CAR O-LINER.	S/N \$ 800.00	?
11	TO SETUP THE VEHICLE ON CAR O-LINER TO FACILITATE THE REPAIR.	S/N \$ 2,400.00	?
12	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N \$ 280.00	X
SUB TOTAL LABOUR CHARGES		: \$ 20,980.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJY 8869 H

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
13	TO CARRY OUT WHEEL ALIGNMENT.	S/N \$ 240.00	?
14	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	/
TOTAL LABOUR CHARGES		: \$ 24,764.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJY 8869 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER / <i>RR</i>	1	\$	1,944.00
2	REAR BUMPER FIXING PARTS / <i>RR</i>	1	\$	201.00
3	REAR BUMPER ADAPTER - LH / RH - <i>MIS</i>	21	\$	84.00
4	REAR BUMPER GUIDE SECTION - LH / RH - <i>MIS</i>	21	\$	36.00
5	REAR BUMPER LOCKING MECHANISM - <i>MIS</i>	1	\$	34.00
6	REAR BUMPER SPOILER / <i>RR</i>	1	\$	264.00
7	REAR LIGHT REFLECTOR - RH - <i>RR</i>	1	\$	46.00
8	TAIL LIGHT OUTER - RH / <i>RR</i>	1	\$	974.00
9	TAIL LIGHT OUTER TRIM - RH - <i>?</i>	1	\$	34.00
10	TAIL LIGHT INNER - RH / <i>RR</i>	1	\$	974.00
11	TAIL LIGHT INNER TRIM - RH - <i>?</i>	1	\$	34.00
12	REAR BUMPER REINFORCEMENT BEAM / <i>RR</i>	1	\$	642.00
13	REAR BUMPER BRACKET - LH / RH - <i>RR</i>	21	\$	63.00
14	REAR BUMPER GUIDE SECTION UPPER - RH - <i>MIS</i>	1	\$	74.00
15	REAR PARKING AID SENSOR - INNER / OUTER - <i>?</i>	2	\$	530.00
16	REAR PARKING AID SENSOR SEAL RING - <i>RR</i>	4	\$	10.00
17	REAR BUMPER WIRING SET - <i>?</i>	1	\$	572.00
18	REAR LID / <i>RR</i>	1	\$	3,657.00
19	REAR LID ATTACHMENT PARTS <i>X</i>	1	\$	308.00
20	REAR LID HINGE - LH / RH <i>X</i>	2	\$	570.00
SUB TOTAL SPARE PARTS		:	\$	11,051.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJY 8869 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR LID FLAP GASKET ?	1	\$ 229.00	
22	REAR PACKING ADHESIVE / NK	1	\$ 21.00	
23	AUDI EMBLEM / NK	1	\$ 144.00	
24	"A3" EMBLEM / NC	1	\$ 104.00	
25	"TFSI" EMBLEM / NC	1	\$ 104.00	
26	REAR FENDER - RH / DD	1	\$ 4,445.00	
27	RIVETTED CAP NUT / NC	2	\$ 7.00	
28	REAR WINDSCREEN / NK	1	\$ 905.00	
29	QUARTER WINDOW - RH / NC	1	\$ 635.00	
30	PRIMER / NK	2	\$ 44.00	
31	GROMMET / NK	2	\$ 4.00	
32	FUEL INSERT / NK (photo)	1	\$ 100.00	
33	BOTTOM PLATE - RH / DD	1	\$ 206.00	
34	REAR WHEEL HOUSING LINER PART - RH REAR	1	\$? 673.00	
35	REAR WHEEL HOUSING LINER CONNECTING PLATE - RH	1	\$? 109.00	
36	D-PILLAR REINFORCEMENT - RH ?	1	\$ 305.00	
37	REAR END PANEL / DD	1	\$ 379.00	
38	REAR END PANEL REINFORCEMENT / DD	1	\$ 773.00	
39	REAR END PANEL CONNECTING PLATE - LH / RH / NK	(2)	\$ 322.00	
40	REAR VENT TRIM / BR	1	\$ 75.00	
SUB TOTAL SPARE PARTS		:	\$ 9,584.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJY 8869 H

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	AERIAL FOR KESSY ?	1	\$	79.00	
42	REAR WHEEL HOUSING LINER / MIS	1	\$	260.00	
43	STONE CHIP / MC	S/N	\$	180.00	
44	METAL FILLER POWDER / MC	S/N	\$	280.00	
45	ARYLIC SEALANT - MC	S/N	\$	180.00	
46	CAVITY WAX - MC	S/N	\$	140.00	
47	1/4 GLASS SEALANT - MC	S/N	\$	100.00	
48	REAR WINDSCREEN SEALANT - MC	S/N	\$	200.00	
49	SUNDRIES ?		\$	400.00	
TOTAL SPARE PARTS		:	\$	22,454.00	
TOTAL LABOUR CHARGES		:	\$	24,764.00	
GRAND TOTAL		:	\$	47,218.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME	:	Steve (LKK)	0D- M M
SURVEYED DATE	:	31/3/22, 12.00pm	EXPIR-?
AUTHORISED DATE	:		P/P
EXCESS COST	:		RL RL y
LIABILITY	:		17 Lys
REMARKS	:		

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT