



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

INV No. AC2202823

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV Date 17/05/2022
Reference CC4/LPC22003006/Rea3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. XE 6910Z
Insured Veh. XE 377C
Claim No. 22/22/22/VC05/0025613
Policy No. Z22VC05010234
Accident Date 26/03/2022
Inspection Date 01/04/2022

Description	Total
Survey Inspection	250.00
Digital Photographs	
Transportation	
Subtotal	250.00
GST (7%)	17.50
Grand Total	267.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC22003006/Rea3q2 Date: 17/05/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XE 377C	Veh. Inspected	XE 6910Z	
Policy No.	Z22VC05010234	Coverage (\$)	0.00	
Claim No.	22/22/22/VC05/0025613	Excess (\$)	0.00	
Assign From	KENNY	Assign Date	31/03/2022	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI FUSO FV70	c.c	10677	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	FV70HJA00212	Colour	WHITE	
Odometer	30350 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5	YOKOHAMA	8 mm	
L/H Front Tyre	295/80 R22.5	YOKOHAMA	8 mm	
R/H Rear Tyre	295/80 R22.5 (D)	YOKOHAMA	8/8 mm	
L/H Rear Tyre	295/80 R22.5 (D)	YOKOHAMA	8/8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/03/2022	Inspection Date	01/04/2022	
Survey held at	GOLDBELL ENGINEERING PTE LTD 8 Tuas Avenue 18 Singapore 638892			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 6910Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	PANEL ASSY ,FR DOOR ,RH	BUCKLED	3,265.58	3,265.58
1	UPP HINGE ,FR DOOR	* CHECK	261.64	-
1	LOWER HINGE ,FR DOOR	* CHECK	261.64	-
1	RUNCHANNEL ,FR DOOR WINDOW GLASS ,RH	NOT NECESSARY	364.41	-
1	WEATHERSTRIP ,FR DOOR OPENING,INR RH	NECESSARY	491.45	491.45
1	MARK ,BLUETEC	NECESSARY	44.83	44.83
1	DECAL ,SHIFT PILOT	NECESSARY	14.99	14.99
1	PANEL ,CAB FR CORNER ,RH	DEFORMED	782.49	782.49
1	WEATHERSTRIP ,CAB FR CORNER PANEL (LONG)	NECESSARY	91.11	91.11
1	WEATHERSTRIP ,CAB FR CORNER PANEL (SHORT)	NECESSARY	28.82	28.82
1	PROTECTOR ,FR PILLAR GARNISH EDGE	NOT NECESSARY	72.89	-
			5,679.85	4,719.27
	<u>LABOUR</u>			
	TO REMOVE AND REFIX DAMAGED PARTS ,CUT ,WELD ,PANEL BEAT ,STRAIGHTEN & REALIGN ,ETC.		1,800.00	1,000.00
	TO CHECK FOR AND RECTIFY WIRING FAULTS ,TO CONDUCT DIAGNOSTICS CHECK.		180.00	60.00
	TO TRANSFER DOOR COMPARTMENT /WINDOW GLASS/REGULATOR/LOCK /MECHANISM ,ETC.		700.00	100.00
	TO PUTTY ,CLEAN SPRAY PAINT AND POLISH ETC.		1,050.00	500.00
			3,730.00	1,660.00
	GRAND TOTAL		9,409.85	6,379.27
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$523.28 NETT)			6,379.27

Report Ref No. CC4/LPC22003006/Rea3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. XE 6910Z

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

