

# AUTOFRANCE

(A Division of Vantage Automotive Limited)

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road Singapore 159942

Tel: 64777409 Fax: 64777398

Date: 24th May 2021

Dear Sir / Madam:

## RE: VEHICLE REPAIR QUOTATION

Owner : Mr Tan Lye Thiam John

Model : FORD FOCUS

Reg. No : SLK1024A

Chassis : WF05XXGCC5GK13783

We are please to submit our estimate of repairs to the abovemention vehicle.

No.	Parts Description	Parts Number	Qty	Price	Cost +
1	WING MIRROR ASSY LH W/O GLASS	BM5117683RG	1		\$620
2	GLASS LH, WING MIRROR	BS7117K741GA	1	\$	320.00
3	W/MIRROR BOTTOM LAMP LH - M08	AU5A13B375AA	1	\$	60.00
4	LAMP LH, WING MIRROR	8M5113B381AC	1	\$	138.00
5	DOOR ASSY - LHR	PBM51A24631BF	1	\$	1,612.00
6	WEATHERSTRIP - BODY RH/LH REAR DOOR	BM51A25324AF	1	\$	226.00
7	PANEL - LH FRT SIDE BODY	BM51A278A99AD	1	\$	2,900.00
8	WEATHERSTRIP - RH/LH FRT/RR DOOR	BM51A20782BC	1	\$	220.00
Total Parts:					<b>\$ 6,096.00</b>

No.	Labour Description	Price
1	LABOUR TO REMOVE & REFIX DOOR LH.	\$ 150.00
1	TO SPRAY PAINT DOOR, ROOF TOP SIDE PANEL AND WING MIRROR.	\$ 525.00
2	TO SUPPLY SEALANT	\$ 60.00
4	TO CUT AND REPLACE LEFT SIDE FRONT BODY PANEL	\$ 2,400.00
		<b>\$ 3,135.00</b>

Sub Total : \$ 9,231.00

GST 7% \$ 646.17

**Grand Total : \$ 9,877.17**

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.

**Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tan Lye Thiam 17445749  
on 4/4/22 @ 530pm  
tanlye@vantage.com  
07 days