



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: YVONNE		Ref: CC4/ASM22003013/Epa3q2 Date: 03/04/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SFP 9981D	Veh. Inspected	SMT 4553K
Policy No.	GA567110	Coverage (\$)	0.00
Claim No.	S2M03X2O	Excess (\$)	0.00
Assign From		Assign Date	31/03/2022
2. Vehicle Particulars & Condition			
Make & Model	B.M.W. X3	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	WBATS720X09B88499	Colour	GREY
Odometer	33137 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/55 R18	MICHELIN	5 mm
L/H Front Tyre	235/55 R18	MICHELIN	5 mm
R/H Rear Tyre	235/55 R18	MICHELIN	5 mm
L/H Rear Tyre	235/55 R18	MICHELIN	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	27/03/2022	Inspection Date	31/03/2022
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	