



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |   |      |                         |            |
|--|---|------|-------------------------|------------|
| CHINA TAIPING INSURANCE (S) PTE LTD<br>3 ANSON ROAD #16-00<br>SPRINGLEAF TOWERSINGAPORE 079909   |   |      | Ref: CS3/CTI22003014/y3 |            |
|  |   |      | Date: 31/03/2022        |            |
|  |   |      | Code: CTI               |            |
| <b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>  |   |      |                         |            |
| Insured Veh.   | GBH 2877H   |      | Veh. Inspected          | SJL 2332Y  |
| Policy No.   |   |      | Coverage (\$)           | 0.00       |
| Claim No.  | SNM22D202168/C02/GBH2877<br>H/TANCHC  |      | Excess (\$)             | 0.00       |
| Assign From  | JACQUELINE TAN  |      | Assign Date             | 31/03/2022 |
| <b>2. Vehicle Particulars &amp; Condition</b>  |   |      |                         |            |
| Make & Model   |   |      | c.c                     | 0          |
| Engine No.   | HIDDEN  |      | Year of Reg.            |            |
| Chassis No.  |   |      | Colour                  |            |
| Odometer   | -   |      | Steering                |            |
| Brakes   |   |      | Modification            |            |
| General  |   |      |                         |            |
| <b>3. Conditions of Tyres</b>  |   |      |                         |            |
|  | Size  | Make | Balance                 |            |
| R/H Front Tyre   |   |      | mm                      |            |
| L/H Front Tyre   |   |      | mm                      |            |
| R/H Rear Tyre  |   |      | mm                      |            |
| L/H Rear Tyre  |   |      | mm                      |            |
| <b>4. Description of Damages</b>   |   |      |                         |            |
|  |   |      |                         |            |
| <b>5. General Information</b>  |   |      |                         |            |
| Accident Date  | 28/03/2022  |      | Inspection Date         | 01/04/2022 |
| Survey held at   | SHENG LI LAI<br>2 KAKI BUKIT AVE 2<br>#01-36 KAKI BUKIT AUTOHUB<br>SINGAPORE 417921 |      |                         |            |
| <b>5a. Remarks</b>   |   |      |                         |            |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.<br>THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.<br>C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. |   |      |                         |            |