



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:YVONNE			Ref: CC4/ASM22003016/Eea3q2 Date: 12/07/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 3787T	Veh. Inspected	GBK 361B
	Policy No.	P2465679	Coverage (\$)	0.00
	Claim No.	S2M03WYI	Excess (\$)	0.00
	Assign From		Assign Date	31/03/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA DYNA 150	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	JTFAT35Y80K214208	Colour	SILVER
	Odometer	77413 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15C	DUNLOP	4 mm
	L/H Front Tyre	195 R15C	DUNLOP	4 mm
	R/H Rear Tyre	195 R15C	DUNLOP	4 mm
	L/H Rear Tyre	195 R15C	DUNLOP	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	26/03/2022	Inspection Date	19/04/2022
	Survey held at	SIN SHENG AUTO WORKSHOP PTE LTD 5 TUAS AVENUE 3, SINGAPORE 639405		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	