

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22003019/UVY3E2

Date: 18/05/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00119662100
Claimant Vehicle No: GBH2370C Insured Vehicle No: GBJ488A
Date of Loss: 29/03/2022 Nature of Claim: TP Claim No: SNM22D202198/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBH2370C
Make & Model: TOYOTA DYNA, 3.0 D (M) Engine No: 1KD2742230
Reg. Date: 21/03/2018 (Man. Year: 2017) Chassis No: KDY2318030894
Colour: Silver Odometer: 165192 km
Engine Capacity: 2982 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/75 R15 Rear Tyre Size: 145 R13 (D)
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6/6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,130.00	972.00	1,158.00	54.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	631.80	197.40	434.40	68.76
Paintwork Labour	691.40	691.40	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,453.20	1,860.80	1,592.40	46.11
Approved Total (Overridden) (\$\$)		1,850.00		
(\$\$)	3,453.20	1,850.00	1,603.20	46.43
+ GST 7.00/7.00% (\$\$)	241.72	129.50	112.22	46.43
Nett Amount (\$\$)	3,694.92	1,979.50	1,715.42	46.43

INSPECTION

Date of Assignment: 31/03/2022 Present Location: Jin Auto Services Pte Ltd (Defu)
Date Inspected: 20/04/2022 Inspected At: Jin Auto Services Pte Ltd (Defu)
Estimated Period of Repair: 4.0 days Blk 14 Defu Lane 10, #01-410/412
Singapore 539195

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Reference		
Part Source:	(Last Synchronised: 18 May 2022)	
Parts:	N/A	TOYOTA DYNA 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH2370C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOTAL PARTS		2,130.00 F	*1,215.00 FL
F=Franchise part. L=ListItemDisc.						
				Sub Total (\$\$)	2,130.00	1,215.00
				- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	243.00
				Total Parts (\$\$)	2,130.00	972.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	TOTAL PAINT LABOUR CHARGE	New	691.40	691.40
<u>Labour Items</u>				
2	TOTAL LABOUR CHARGE	New	631.80	197.40
Gross Labour Cost (S\$)			1,323.20	888.80

Report was unsubmitted during this print-out.

< END OF ESTIMATES >