

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0250/2022/JT
DATE	:	30-Mar-22
WIP	:	17306

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 31/3/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME	:	MS CHEOK SUAT LEE
ADDRESS	:	68 ST. THOMAS WALK #03-01 SINGAPORE 238142
TELEPHONE	:	HP +65 96810102
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	1800055715-03
VEHICLE NO	:	SBN 8881 Z
MODEL CODE	:	AUDI Q5 2.0 TFSI QU
MODEL YEAR	:	17/5/2018
ENGINE NO	:	DAX 033228
CHASSIS NO	:	WAYZZZFY3J2141016
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	26-Mar-22
PLACE OF ACCIDENT	:	FAR EAST PLAZA CAR PARK

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SBN 8881 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	✓
2	TO RENEW LHS 1/4 GLASS TO FACILITATE THE RENEWAL OF LHS REAR FENDER.	S/N \$	300.00	✓
3	TO INSTALL SOLAR FILM FOR LHS 1/4 GLASS.	S/N \$	400.00	✓
4	TO CARRY OUT WATER SEEPAGE TEST FOR 1/4 GLASS.	S/N \$	200.00	150 ✓
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,400.00	✓
TOTAL LABOUR CHARGES		:	\$ 2,660.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SBN 8881 Z

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$ 1,400.00 ✓	✓
7	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 800.00 560 ✓	✓
8	TO DISMANTLE AND RENEW REAR BUMPER, LHS REAR DOOR AND LHS FRONT DOOR. TO CUT OUT AND WELD LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 7,200.00 4000 ✓	✓
9	TO RESPRAY REAR BUMPER, LHS REAR FENDER, DOOR HANDLE, LHS REAR DOOR, LHS FRONT DOOR, 2 DOOR COVERS, LHS SILL PANEL, ROOF CHANNEL, DRAIN CHANNEL, DOOR ENTRANCE, REAR END PANELLING AND BOTH REAR WHEEL ARCHTRIMS.	\$ 9,000.00	$5.5 \times 850 = 3025$ Wheel Arch x 2 = 400 Door Cover x 2 = 400 <u>3825</u> ✓
10	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 21,252.00	

55, UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SBN 8881 Z - REAR

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	REAR BUMPER <i>rehand</i>	1	\$ 2,030.00	✓	1624
2	REAR BUMPER TAIL LIGHT - LH <i>not new</i>	1	\$ 779.00	+	
3	TAIL LIGHT - LH <i>nt</i>	1	\$ 1,859.00	✓	1487.20
4	REAR BUMPER GUIDE SECTION - LH <i>?</i>	1	\$ 95.00	?	75.28
5	REAR WHEEL ARCH COVER - LH / RH <i>new</i>	2	\$ 1,230.00	✓	984
6	REAR VENT TRIM <i>new</i>	1	\$ 75.00	+	
7	REAR FENDER - LH <i>Dented</i>	1	\$ 5,267.00	✓	4213.60
8	QUARTER WINDOW - LH <i>new</i>	1	\$ 925.00	✓	740
9	REAR DOOR - LH <i>Distorted</i>	1	\$ 4,390.00	✓	3512
10	REAR DOOR SEAL BRACKET <i>?</i>	1	\$ 48.00	?	X
11	REAR DOOR OUTER SEAL - LH <i>new</i>	1	\$ 229.00	✓	182.80
12	BONDING AGENT <i>?</i>	1	\$ 51.00	?	X
13	CLEANING SOLUTION <i>?</i>	1	\$ 74.00	?	X
14	APPLICATOR <i>?</i>	1	\$ 8.00	?	X
15	REAR DOOR SEALING STRIP <i>new</i>	1	\$ 19.00	+	
16	GROMMET <i>?</i>	3	\$ 10.00	?	X
17	REAR DOOR ATTACHMENT PARTS <i>not new</i>	1	\$ 231.00	+	
18	REAR DOOR CATCH - LH <i>?</i>	1	\$ 163.00	?	X
19	REAR DOOR SEAL OUTER - LH <i>?</i>	1	\$ 247.00	?	X
20	REAR DOOR HINGE HALF UPPER / LOWER - LH <i>new</i>	2	\$ 106.00	+	
SUB TOTAL SPARE PARTS			\$ 17,836.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SBN 8881 Z - REAR

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	REAR DOOR SEAL INNER - LH <i>ren</i>	1	\$	229.00	+
22	REAR DOOR HANDLE MOUNTING BAR - LH <i>ren</i>	1	\$	183.00	x
23	REAR DOOR WINDOW REGULATOR - LH <i>ren</i>	1	\$	334.00	+
24	REAR DOOR SILL TRIM STRIP - LH <i>ren</i>	1	\$	158.00	✓ 126.40
25	REAR DOOR COVER - LH <i>ren</i>	1	\$	728.00	✓ 582.40
SUB TOTAL SPARE PARTS		:	\$	1,632.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED; REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SBN 8881 Z - FRONT

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT DOOR - LH <i>Distorted</i>	1	\$ 4,390.00	✓ 3512
2	FRONT DOOR BUNGS - LH <i>new</i>	1	\$ 5.00	+
3	FRONT DOOR OUTER SEAL - LH <i>new</i>	1	\$ 229.00	✓ 182.80
4	BONDING AGENT ?	1	\$ 51.00	? X
5	CLEANING SOLUTION ?	1	\$ 74.00	? X
6	APPLICATOR ?	1	\$ 8.00	? X
7	GROMMET ?	5	\$ 16.00	? X
8	FRONT DOOR ATTACHMENT PARTS <i>new</i>	1	\$ 276.00	X
9	FRONT DOOR CATCH - LH ?	1	\$ 163.00	? X
10	FRONT DOOR COVER - LH <i>new</i>	1	\$ 833.00	✓ 666.40
11	FRONT DOOR HANDLE TRIM PLATE - PASSENGER SIDE <i>new</i>	1	\$ 306.00	+
12	FRONT DOOR HOUSING - PASSENGER SIDE <i>Not new</i>	1	\$ 20.00	+
13	FRONT DOOR HANDLE COVER - LH <i>new</i>	1	\$ 7.00	X
14	FRONT DOOR HANDLE MOUNTING BAR - PASSENGER SIDE <i>new</i>	1	\$ 183.00	+
15	STONE CHIP	S/N	\$ 180.00	✓ 180
16	METAL FILLER POWDER	S/N	\$ 280.00	✓ 280
17	ARYLIC SEALANT	S/N	\$ 180.00	✓ 180
18	CAVITY WAX	S/N	\$ 140.00	✓ 140
19	1/4 GLASS SEALANT	S/N	\$ 100.00	✓ 100
20	SUNDRIES ?		\$ 500.00	? 57.60
TOTAL SPARE PARTS		:	\$ 27,409.00	
TOTAL LABOUR CHARGES		:	\$ 21,252.00	
GRAND TOTAL		:	\$ 48,661.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

 PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adnan L
SURVEYED DATE : 31/03/22
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 14 Days

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: