

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22003023/AQCE2**Date:** 30/09/2022**REFERENCE**

Insured/Claimant:	CHEN JUNMING	Policy No:	2070177852	
Date of Loss:	25/03/2022	Nature of Claim:	OD	Claim No: 4021261129SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX616T		
Make & Model:	AUDI A1 SPORTBACK, 1.0 TFSI S-tronic (A)	Engine No:	DKJ052759
Reg. Date:	23/12/2020 (Man. Year: 2020)	Chassis No:	WAUZZZGB9LR044567
Colour:	Red	Odometer:	23459 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$120,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/55 R16	Rear Tyre Size:	195/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,319.00	2,696.88	4,622.12	63.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,952.00	1,602.00	2,350.00	59.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,271.00	4,298.88	6,972.12	61.86
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	10,971.00	3,998.88	6,972.12	63.55
+ GST 7.00/7.00% (S\$)	767.97	279.92	488.05	63.55
Nett Amount (S\$)	11,738.97	4,278.80	7,460.17	63.55

INSPECTION

Date of Assignment:	01/04/2022		
Date Inspected:	31/03/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,317.00 FS	*1,853.60 FS
2	1		*REAR BUMPER ADAPTER-RH	Not Necessary	24.00 FS	*- FS
3	1		*REAR BUMPER DIFFUSER	Cut	469.00 FS	*374.80 FS
4	1		*REAR BUMPER GRILLE-RH	Cut	253.00 FS	*202.40 FS
5	1		*REAR BUMPER TRIM-CENTER	Cut	239.00 FS	*190.80 FS
6	1		*REAR BUMPER GRILLE-CENTER	Not Necessary	96.00 FS	*- FS
7	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	564.00 FS	*- FS
8	1		*REAR BUMPER SECURING STRIP-CENTER	Not Necessary	151.00 FS	*- FS
9	1		*REAR BUMPER GUIDE SECTION-RH	Not Necessary	54.00 FS	*- FS
10	1		*REAR BUMPER GUIDE PROFILE-RH	Not Necessary	63.00 FS	*- FS
11	2		*REAR PARKING AID SENSOR	Not Necessary	530.00 FS	*- FS
12	4		*REAR PARKING AID SENSOR SEAL RING	Not Necessary	10.00 FS	*- FS
13	1		*TAIL LIGHT OUTER-RH	Not Necessary	898.00 FS	*- FS
14	1		*TAIL LIGHT OUTER TRIM-RH	Not Necessary	34.00 FS	*- FS
15	1		*TAIL LIGHT INNER-RH	Not Necessary	898.00 FS	*- FS
16	1		*REAR PARKING ADHESIVE	Not Necessary	21.00 FS	*- FS
17	1		*AUDI ENBLEM	Not Necessary	144.00 FS	*- FS
18	1		*A1 ENBLEM	Not Necessary	104.00 FS	*- FS
19	1		*REAR NO PLATE	Not Necessary	60.00 FS	*- FS
20	1		*SUNDRIES	Necessary	300.00 FS	*3.52 FS
21	1		*UNDERBODY TRIM - RH REAR (Supplementary)	Torn	90.00 FS	*71.76 FS
F=Franchise part. S=SpcNett.						
					Total Parts (\$\$)	7,319.00 2,696.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND RENEW REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER.TO REPAIR REAR LID.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,400.00	500.00
3	TO RESPRAY REAR BUMPER AND REAR LID	New	2,000.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			3,952.00	1,602.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >