



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0248/2022/JT
DATE	:	29-Mar-22
WIP	:	17581

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 31/3/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME	:	MR CHIA JIE EN, EDWIN
ADDRESS	:	BLK 103A BIDADARI PARK DRIVE #11-21 SINGAPORE 341103
TELEPHONE	:	HP +65 84982925
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	
VEHICLE NO	:	SMZ 4169 E
MODEL CODE	:	AUDI A4 2.0 TFSI S TRONIC
MODEL YEAR	:	26/4/2021
ENGINE NO	:	DEM 024276
CHASSIS NO	:	WAUZZZF42LN014594
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	28-Mar-22
PLACE OF ACCIDENT	:	BIDADARI PARK DRIVE CAR PARK SLOPE

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMZ 4169 E

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 ✓	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00 250 ✓	✓
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,100.00 1000 ✓	✓
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$ 2,000.00 1100 ✓	✓
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ <u>5,122.00</u>	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 4169 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Replaced</i>	1	\$ 2,377.00	✓ 1901.60
2	FRONT BUMPER FIXING PARTS <i>Replaced</i>	1	\$ 393.00	X
3	FRONT BUMPER SECURING STRIP <i>? nn</i>	2	\$ 79.00	? X
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>1/2</i>	1	\$ 293.00	+.
5	FRONT BUMPER AIR GUIDE - RH <i>Missing</i>	1	\$ 51.00	✓ 40.08
6	FRONT BUMPER AIR GUIDE GRILLE - RH <i>Missing</i>	1	\$ 151.00	✓ 120.40
7	FRONT BUMPER TRIM - RH <i>Missing</i>	1	\$ 54.00	✓ 42.64
8	FRONT BUMPER GUIDE SECTION - RH <i>? nn</i>	1	\$ 41.00	? X
9	FRONT BUMPER FOAM FILLER PIECE <i>Replaced</i>	1	\$ 212.00	+
10	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 899.00	+
11	FRONT BUMPER TOP COVER <i>Replaced</i>	1	\$ 143.00	+
12	CAUTION STICKER <i>Replaced</i>	1	\$ 16.00	+
13	AIR COND STICKER	1	\$ 9.00	+
14	FRONT PARKING AID SENSOR OUTER <i>Replaced</i>	1	\$ 265.00	+
15	FRONT PARKING AID SENSOR SEAL RING <i>Replaced</i>	4	\$ 10.00	+
16	HORN - RH <i>Replaced</i>	1	\$ 139.00	+
17	HORN SUPPORT - RH <i>Replaced</i>	1	\$ 33.00	+
18	FRONT FENDER - RH <i>Dented</i>	1	\$ 1,227.00	✓ 981.60
19	FRONT FENDER ATTACHMENT PARTS <i>Replaced</i>	1	\$ 211.00	+
20	FRONT FENDER CLOSING ELEMENT - RH <i>Replaced</i>	1	\$ 81.00	+
SUB TOTAL SPARE PARTS		:	\$ 6,684.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 4169 E

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	FRONT FENDER BRACKET - RH <i>xcu</i>	1	\$ 41.00	+	
22	FRONT FENDER POP RIVET <i>xcu</i> nec	6	\$ 23.00	+	18.24
23	FRONT FENDER BRACE - RH <i>xcu</i> bent	1	\$ 132.00	+	105.20
24	FRONT WHEEL HOUSING LINER - RH	1	\$ 262.00	+	
25	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>3 x 1 m</i>	1	\$ 149.00	+	
26	FRONT WHEEL SPOILER - RH	1	\$ 82.00	+	
27	FRONT WHEEL SPOILER LOWER - RH <i>3 x 1 m</i>	1	\$ 40.00	+	
28	FRONT FENDER LEDGE COVER LONG - RH <i>2 ? nn</i>	1	\$ 35.00	+	? X
29	HEADLAMPS COVER - RH <i>xcu</i>	1	\$ 49.00	+	
30	HEADLIGHT - RH <i>ct</i>	1	\$ 8,172.00	+	6537.60
31	LIFT CYLINDER - RH <i>3 x 1 m</i>	1	\$ 231.00	+	
32	LIFT CYLINDER BRACKET - RH <i>xcu</i>	1	\$ 7.00	+	
33	LIFT CYLINDER CORRUGATED PIPE <i>xcu</i>	1	\$ 107.00	+	
34	SUNDRIES <i>?</i> nec		\$ 300.00	+	X
TOTAL SPARE PARTS			: \$ 16,314.00		
TOTAL LABOUR CHARGES			: \$ 5,122.00		
GRAND TOTAL			: \$ 21,436.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

 PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

:
:
:
:
:
:

Adrian
31/03/22

Not Authorised, 04 Days

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: