

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22003027/ATCE2

Date: 24/06/2022

REFERENCE

Insured/Claimant:	FU GUOHONG	Policy No:	7210151128		
Date of Loss:	29/03/2022	Nature of Claim:	OD	Claim No:	4336757306SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SND3442B		
Make & Model:	AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17) (A)	Engine No:	CZDC54127
Reg. Date:	23/12/2021 (Man. Year: 2021)	Chassis No:	WAUZZZF30N1038135
Colour:	Blue	Odometer:	4698 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$195,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65 R17	Rear Tyre Size:	215/65 R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,931.00	5,851.20	3,079.80	34.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,192.00	3,652.00	4,540.00	55.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,123.00	9,503.20	7,619.80	44.50
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	16,723.00	9,103.20	7,619.80	45.56
+ GST 7.00/7.00% (S\$)	1,170.61	637.22	533.39	45.57
Nett Amount (S\$)	17,893.61	9,740.42	8,153.19	45.56

INSPECTION

Date of Assignment:	01/04/2022		
Date Inspected:	31/03/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR - LH	Dented	3,017.00 FS	*2,413.60 FS
2	1		*FRONT DOOR OUTER SEAL - LH	Necessary	185.00 FS	*147.60 FS
3	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	164.00 FS	*- FS
4	1		*FRONT DOOR CATCH - LH	Not Necessary	134.00 FS	*- FS
5	1		*FRONT DOOR COVER - LH	Cut	283.00 FS	*226.00 FS
6	1		*REAR DOOR - LH	Distorted	3,127.00 FS	*2,501.60 FS
7	1		*REAR DOOR OUTER SEAL - LH	Necessary	151.00 FS	*120.40 FS
8	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	324.00 FS	*- FS
9	1		*REAR DOOR CATCH - LH	Not Necessary	134.00 FS	*- FS
10	1		*REAR DOOR SILL PANEL SEAL - LH	Not Necessary	151.00 FS	*- FS
11	1		*REAR DOOR COVER - LH	Deformed	270.00 FS	*216.00 FS
12	2		*REAR DOOR HINGE HALF UPPER / LOWER - LH LOWER	Not Necessary	102.00 FS	*- FS
13	1		*REAR WHEEL ARCH COVER - LH	Cut	283.00 FS	*226.00 FS
14	1		*REAR WHEEL SPOILER - LH	Not Necessary	44.00 FS	*- FS
15	1		*REAR WHEEL HOUSING LINER - LH	Not Necessary	262.00 FS	*- FS
16	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	8,931.00 5,851.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	800.00	560.00
2	TO DISMANTLE AND RENEW LHS FRONT DOOR AND LHS REAR DOOR. TO REPAIR LHS B-PILLAR AND LHS REAR FENDER RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,200.00	1,250.00
3	TO RESPRAY LHS FRONT DOOR, LHS REAR DOOR, HINGES, LHS B-PILLAR AND LHS REAR FENDER	New	4,000.00	1,650.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			8,192.00	3,652.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >