

ASS. F. No.:


REF: CCG/ALG22003037 Dpa³

ASSIGNMENT

From: _____ Date: _____
 Estimation Cost: _____
 OD / IE / WS / P RES / DD RES / EVA / RV / MV
 To inspect Vehicle No: _____
 at W/O: _____
 of: _____
 Insurance: _____
 Policy No: _____
 Claims to: _____
 Sum Insured: _____ Excess: _____
 (Check record)
 Make/Model: _____

(Police Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. of Market Value:

IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seat: _____ Consistent? : Yes or No
 Est. Repair: 4 days Res.: Yes or No
 Ltra Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJW 4477S Yr Regn: May / 2017
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Kia Cerato K3 cc 1591
 Colour: Grey A/C: Insured / Std / N/A
 Sp. Reading: 263757 T/Radio: Insured / Std / N/A
 Eng/No: G4FGG+1641704
 C/No: KNAFX411M+15720676

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NH / B/Arm / STD A/Rim or

Type Size: F: 205/55 R16
 R: 11

BS / DUN / EXNOVA / GY / PS / LIZA / MIC / DHTSU / PR / SURE /
 TOYO / YOKO or Yokohama

Front

Rear

R/Bal: S mm R/Bal: S mm

L/Bal: S mm L/Bal: S mm

D.O.A: 30/03/2022 D.O.I: 01/04/2022

Survey held at: At the And AMK

Des. of Damages: Fnt / Rear / O/S / N/S / W/C / Rooftop or

Rear

The W/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

ALG GBH 6587T

MV 561K

LTA 36.2K

HL 19.8K

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee:

Transportation

2)

Add Fee: ☐ : Site Insp (\$)

S + RS



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



BATTERY

Reference No.: 310322

Date: 31.03.2022

Tan Boon Ann


Blk 74 Whampoa Drive #10-322

Singapore 320074

KIA Cerato K3

Estimate Repair Cost for Vehicle Reg. No: SJW 4477 S

1 Pc. Rear Boot <i>Dent</i>		1,388.00	✓
2 Pcs. Rear Boot Hinger <i>HH</i>	@ 74.00	148.00	X
1 Pc. Rear Boot KIA Logo <i>HH</i>		37.00	✓
1 Pc. Rear Boot Cerato K3 Emblem <i>HH</i>		34.00	X
1 Pc. Rear C&C Logo <i>HH</i>		16.00	X
2 Pcs. Rear Boot Lamp <i>mainly broken</i>	@ 580.00	1,160.00	✓
2 Pcs. Rear Boot No. Plate Lamp <i>HH</i>	@ 38.00	76.00	X
1 Pc. Rear Boot Reverse Cam <i>HH</i>		297.00	X
2 Pcs Rear Boot Stopper <i>HH</i>	@ 12.00	24.00	X
1 Pc. Rear Boot Lock <i>Draw</i>		149.00	✓
1Pc. Rear Boot Opener Switch <i>HH</i>		69.00	X
1 Pc. Rear Boot Handle <i>HH</i>		38.00	X
1 Pc. Rear Boot inner Garnish <i>HH</i>		221.00	X
12 Pcs. Rear Boot Inner Garnish Clips <i>HH</i>	@ 5.00	60.00	X
2 Pcs. Rear Lamp <i>mainly broken</i>	@ 639.00	1,278.00	✓
2 Pcs. Rear Lamp Panel <i>HH</i>	@ 210.00	420.00	X
1 Pc. Rear Weather Slip <i>HH</i>		105.00	X
1 Pc. Rear Support Panel <i>HH</i>		347.00	X
1 Pc. Rear Support Panel Garnish <i>mainly damaged</i>		58.00	✓
1 Pc. Rear Support Panel Lock Catch <i>HH</i>		28.00	X
1 Pc. Rear Spare Tank Floor Panel <i>HH</i>		714.00	X
1 Pc. Rear Spare Tank Tools Sponge <i>HH</i>		290.00	X
1 Pc. Rear Spare Tank Insulator <i>HH</i>		280.00	X
1 Pc. Rear Spare Tank Dust Garnish <i>HH</i>		49.00	X
6 Pcs. Rear Spare Tank Dust Garnish Clips <i>HH</i>	@ 5.00	30.00	X
1 Pc. Rear Spare Tyre Cover <i>HH</i>		280.00	X
1 Pc. Windscreen Moulding <i>HH</i>		45.00	X
1 Pc. Windscreen Seal <i>HH</i>		28.00	X
1 Pc. Windscreen Sealant <i>HH</i>		120.00	X
2 Pcs. Rear Fender <i>HH</i>	@ 1,224.00	2,448.00	X
10 Pcs. Rear Fender Dust Garnish Clips <i>HH</i>	@ 5.00	50.00	X



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



BATTERY

2 Pcs. Rear Fender Inner Garnish Trim HH	@ 181.00	362.00	X
20 Pcs. Rear Fender Inner Garnish Clips HH	@ 5.00	100.00	X
1 Pc. Rear Fender Air Duct (RH) HH		128.00	X
1 Pc. Rear Bumper <i>distorted</i>		737.00	✓
1Pc. Rear Bumper Sponge HF		299.00	X
1 Pc. Rear Bumper Reinforcement <i>chrome</i>		346.00	✓
4 Pcs. Rear Bumper Lower Bracket <i>SH</i>	@ 32.00	128.00	X
1 Set Rear Bumper Parking Sensor <i>Down</i>		380.00	✓ 220/- SH
1 Pc. Rear Bumper Spoiler <i>distorted / damaged</i>		1,050.00	✓
2 Pcs. Rear Bumper Reflector HH	@ 132.00	264.00	X
10 Pcs. Rear Bumper Clips HH	@ 5.00	50.00	20/- SH
1 Pc. Rear Exhaust HH		591.00	X
4 Pcs. Rear Exhaust Mounting HH	@ 24.00	96.00	X
1 Pc. Rear Exhaust Centre Pipe HH		661.00	X
1 Pc. Rear Exhaust Aluminum Heat Shield HH		141.00	X
1 Set Rear Tough Coat Shield HH		400.00	X
1 Pc. Rear No. Plate & Box HH		50.00	X
2 Pcs. Rear Big Bracket <i>p/s broken H/S HH</i>	@ 98.00	196.00	✓

Total (Panels / Parts): 16,266.00 (SGD)

LABOR CHARGES

To check wiring, remove & refit & check SRS, ABS, Sensor, head lamp sensor, room, tail lamp & resetting & erase fault code.	480.00 40/-
To remove & refit windscreen.	180.00 HH
To remove & refit interior garnish, carpet, cushion, & All accident affected area.	280.00 80/-
To remove & refit exhaust pipe, box & all affected area.	220.00 HH
To remove & refit rear undercarriage & affected damage Area.	400.00 HH
To welding, knocking, straightening repair & renew all Accident damaged affected area.	1,200.00 600/-



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com



To respray painting on all accident affected area.
(Front/Rear) (Pearl)

~~1,400.00~~ 600/-

To rust proof all accident affected area.

~~250.00~~ 40/-

Total (Labor Charges): **4,410.00 (SGD)**

TOTAL COST SUMMARY

PANELS / PARTS	16,266.00
LABOR CHARGES	4,410.00

Grand Total: **20,676.00 (SGD)**

We shall be glad if you can forward the payment at your early convenience.

**For internet banking transfer – OCBC Current Account No. 620-453233-001 or
PAYNOW UEN 39108900E**

ACKNOWLEDGED BY	DATE	ALFRED AUTO SERVICES & SUPPLIES
		Alfred Quah

Note: Full payment must be completed 7 days from the invoice date. There will be an interest of 1.5% imposed per month on overdue invoice. Thank you.

01/04/2022 e 1700

Hot Antenna

2/Sum

nyan 4 days.

2kk Auto