



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



BATTERY



Reference No.: 310322

Date: 31.03.2022

Tan Boon Ann

Blk 74 Whampoa Drive #10-322

Singapore 320074

KIA Cerato K3

Estimate Repair Cost for Vehicle Reg. No: SJW 4477 S

1 Pc. Rear Boot <i>Dent</i>		1,388.00	✓	1297.90
2 Pcs. Rear Boot Hinger <i>HH</i>	@ 74.00	148.00	X	
1 Pc. Rear Boot KIA Logo <i>HH</i>		37.00	✓	
1 Pc. Rear Boot Cerato K3 Emblem <i>HH</i>		34.00	X	
1 Pc. Rear C&C Logo <i>HH</i>		16.00	X	
2 Pcs. Rear Boot Lamp <i>mainly broken</i>	@ 580.00	1,160.00	✓	
2 Pcs. Rear Boot No. Plate Lamp <i>HH</i>	@ 38.00	76.00	X	
1 Pc. Rear Boot Reverse Cam <i>HH</i>		297.00	X	
2 Pcs Rear Boot Stopper <i>HH</i>	@ 12.00	24.00	X	
1 Pc. Rear Boot Lock <i>Dent</i>		149.00	✓	
1Pc. Rear Boot Opener Switch <i>HH</i>		69.00	X	
1 Pc. Rear Boot Handle <i>HH</i>		38.00	X	
1 Pc. Rear Boot inner Garnish <i>HH</i>		221.00	X	
12 Pcs. Rear Boot Inner Garnish Clips <i>HH</i>	@ 5.00	60.00	X	
2 Pcs. Rear Lamp <i>mainly broken</i>	@ 639.00	1,278.00	✓	
2 Pcs. Rear Lamp Panel <i>HH</i>	@ 210.00	420.00	X	
1 Pc. Rear Weather Slip <i>HH</i>		105.00	X	
1 Pc. Rear Support Panel <i>HH</i>		347.00	X	
1 Pc. Rear Support Panel Garnish <i>mainly damaged</i>		58.00	✓	
1 Pc. Rear Support Panel Lock Catch <i>HH</i>		28.00	X	
1 Pc. Rear Spare Tank Floor Panel <i>HH</i>		714.00	X	
1 Pc. Rear Spare Tank Tools Sponge <i>HH</i>		290.00	X	
1 Pc. Rear Spare Tank Insulator <i>HH</i>		280.00	X	
1 Pc. Rear Spare Tank Dust Garnish <i>HH</i>		49.00	X	
6 Pcs. Rear Spare Tank Dust Garnish Clips <i>HH</i>	@ 5.00	30.00	X	
1 Pc. Rear Spare Tyre Cover <i>HH</i>		280.00	X	
1 Pc. Windscreen Moulding <i>HH</i>		45.00	X	
1 Pc. Windscreen Seal <i>HH</i>		28.00	X	
1 Pc. Windscreen Sealant <i>HH</i>		120.00	X	
2 Pcs. Rear Fender <i>HH</i>	@ 1,224.00	2,448.00	X	
10 Pcs. Rear Fender Dust Garnish Clips <i>HH</i>	@ 5.00	50.00	X	



ALFRED AUTO

Services & Supplies

BK 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
 Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
 Email: alfredauto@hotmail.com

Tyre &
Sports Rim



2 Pcs. Rear Fender Inner Garnish Trim HH	@ 181.00	362.00	X
20 Pcs. Rear Fender Inner Garnish Clips HH	@ 5.00	100.00	X
1 Pc. Rear Fender Air Duct (RH) HH		128.00	X
1 Pc. Rear Bumper <i>distm</i>		737.00	✓
1Pc. Rear Bumper Sponge HF		299.00	X
1 Pc. Rear Bumper Reinforcement <i>CRAC</i>		346.00	✓
4 Pcs. Rear Bumper Lower Bracket <i>SH</i>	@ 32.00	128.00	X
1 Set Rear Bumper Parking Sensor <i>DM</i>		380.00 ✓	220/- SH
1 Pc. Rear Bumper Spoiler <i>distm / dymel</i>		1,050.00 ✓	347.90
2 Pcs. Rear Bumper Reflector HH	@ 132.00	264.00	X
10 Pcs. Rear Bumper Clips HH	@ 5.00	50.00 20/-	SH
1 Pc. Rear Exhaust HH		591.00	X
4 Pcs. Rear Exhaust Mounting HH	@ 24.00	96.00	X
1 Pc. Rear Exhaust Centre Pipe HH		661.00	X
1 Pc. Rear Exhaust Aluminum Heat Shield HH		141.00	X
1 Set Rear Tough Coat Shield HH		400.00	X
1 Pc. Rear No. Plate & Box HH		50.00	X
2 Pcs. Rear Big Bracket <i>p/s broken H/SH</i>	@ 98.00	196.00 ✓	98.00

Total (Panels / Parts): **16,266.00 (SGD)**

SH - 240.00 ✓ List 5508.80
10% 4957.92 ✓

LABOR CHARGES

To check wiring, remove & refit & check SRS, ABS, Sensor, head lamp sensor, room, tail lamp & resetting & erase fault code.	480.00 40/-
To remove & refit windscreen.	180.00 HH
To remove & refit interior garnish, carpet, cushion, & All accident affected area.	280.00 80/-
To remove & refit exhaust pipe, box & all affected area.	220.00 HH
To remove & refit rear undercarriage & affected damage Area.	400.00 HH
To welding, knocking, straightening repair & renew all Accident damaged affected area.	1,200.00 600/-



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



To respray painting on all accident affected area.
(Front/Rear) (Pearl)

1,400.00 600/-

To rust proof all accident affected area.

250.00 40/-

1360.00 //

Total (Labor Charges): 4,410.00 (SGD)

TOTAL COST SUMMARY

PANELS / PARTS 16,266.00
LABOR CHARGES 4,410.00

Grand Total: 20,676.00 (SGD)

6557.92

symp

380.00

6937.92

We shall be glad if you can forward the payment at your early convenience.

For internet banking transfer – OCBC Current Account No. 620-453233-001 or
PAYNOW UEN 39108900E

4/5 5550.00 //

ACKNOWLEDGED BY	DATE	ALFRED AUTO SERVICES & SUPPLIES
		Alfred Quah

Note: Full payment must be completed 7 days from the invoice date. There will be an interest of 1.5% imposed per month on overdue invoice. Thank you.

01/04/2022 e 1700

Hot Antenna

2/Share

5 days.

nyu

LKK Auto

Page 3 of 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391069/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



Reference No.: 310322

Date: 31.03.2022

Tan Boon Ann

Blk 74 Whampoa Drive #10-322

Singapore 320074

KIA Cerato K3

Supplementary Repair Cost for Vehicle Reg. No: SJW 4477 S

1 Set. Reverse Camera <i>Don</i>	390.00 ✓ 350/- SN
1 Pc. Reverse Camera Harness Wire <i>HN</i>	149.00 X

Total (Panels / Parts): 539.00 (SGD)

LABOR CHARGES

To remove & renew reverse camera & harness wire.	180.00 30/-
--	------------------------

Total (Labor Charges): 180.00 (SGD)

TOTAL COST SUMMARY

PANELS / PARTS <i>1 ngn</i>	539.00
LABOR CHARGES	180.00

2kk Auto Grand Total: 719.00 (SGD)

We shall be glad if you can forward the payment at your early convenience.

For internet banking transfer – OCBC Current Account No. 620-453233-001 or
PAYNOW UEN 39108900E

ACKNOWLEDGED BY	DATE	ALFRED AUTO SERVICES & SUPPLIES
		<i>Alfred Quah</i>

Note: Full payment must be completed 7 days from the invoice date. There will be an interest of 1.5% imposed per month on overdue invoice. Thank you.