

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6844 4625 Email: claims@focusauto.com.sg

INDIA INTERNATIONAL INSURANCE PTE LTD

64 Cecil Street
#04, #05
IOB Building
Singapore 049711

Estimate No : E22030073

Date : 29/03/2022

Veh Reg No : **SMC 4137 T**

Make / Model : **TOYOTA C-HR
HYBRID 1.8S CVT**

Chassis No. : ZYX102125088

Engine No. : 2ZR2A00740

Reg. Date : 29/06/2018

ATTN : Motor Claim Department
Your Ref No. : **SLP 4385 L**
Claim Type : THIRD PARTY
Accident Date : 25/03/2022

*Not Added
1/4/22
2/5# 17,800/
13 days*

Estimate Repair Cost to Vehicle No : SMC 4137 T

LIST PRICE

		Quantity	Unit	Price	Amount
				SS	SS
1	Front Bonnet <i>sal</i>	1	PCS	1,806.20	1,806.20
2	Front Bonnet Lock <i>sent</i>	1	PCS	124.10	124.10
3	Front Bonnet Hinge <i>sent/ty</i>	2	PCS	65.40	130.80
4	Front Bonnet Insulator <i>waged</i>	1	PCS	313.40	313.40
5	Front Bonnet Insulator Clip <i>na</i>	10	PCS	12.90	129.00
6	Front Centre Brace <i>cre</i>	1	PCS	129.50	129.50
7	Front Support Panel <i>sent</i>	1	PCS	819.40	819.40
8	Front Support Panel Top Garnish <i>dis</i>	1	PCS	329.50	329.50
9	Front Support Panel Top Garnish Clip <i>11</i>	6	PCS	11.30	67.80
10	Front Headlamp <i>holder cr</i>	2	PCS	2,145.40	4,290.80
11	Front Grille <i>cr</i>	1	PCS	245.10	245.10
12	Front Grille Garnish <i>cre</i>	1	PCS	345.10	345.10
13	Front Grille Centre Emblem <i>cre</i>	1	PCS	1,062.40	1,062.40
14	Front Grille Top Rubber <i>11</i>	1	PCS	110.40	110.40
15	Front Housing Support Beam - RH <i>sent</i>	1	PCS	240.10	240.10
16	Front Housing Support Beam - LH <i>sent</i>	1	PCS	240.10	240.10
17	Front Bumper <i>dis</i>	1	PCS	880.40	880.40
18	Front Bumper Inner Top Beam <i>sent</i>	1	PCS	239.40	239.40
19	Front Bumper Top Inner Air Duct <i>dis</i>	1	PCS	110.40	110.40
20	Front Bumper Reinforcement <i>sent</i>	1	PCS	399.40	399.40
21	Front Bumper Inner Sponge <i>ty</i>	1	PCS	110.40	110.40
22	Front Bumper Centre Grille <i>sent/ty</i>	1	PCS	405.10	405.10
23	Front Bumper Reinforcement Bracket <i>sent</i>	2	PCS	124.10	248.20
24	Front Bumper Side Cover - RH <i>mis</i>	1	PCS	110.40	110.40
25	Front Bumper Side Retainer <i>sent</i>	2	PCS	110.30	220.60
26	Front Number Plate Support <i>re</i>	1	PCS	124.40	124.40
27	Front Fender - RH <i>r</i>	1	PCS	727.40	727.40
28	Front Fender Protector - RH <i>11</i>	1	PCS	201.10	201.10
29	Front Fender Emblem - RH <i>11</i>	1	PCS	45.90	45.90
30	Front Air Cleaner Box <i>crq</i>	1	PCS	809.40	809.40
31	Front Air Cleaner Air Duct <i>twl</i>	1	PCS	140.20	140.20
32	Front Air Cleaner Air Duct Panel <i>dis</i>	1	PCS	160.40	160.40
33	Front Air-Con Condenser <i>sent/pnn</i>	1	PCS	1,204.10	1,204.10

13486.9

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6844 4625 Email: claims@focusauto.com.sg

34	Front Air-Con Air Sensor	cre	1	PCS	303.40	303.40
35	Front Air-Con Condenser Side Garnish - RH	D/S	1	PCS	124.40	124.40
36	Front Air-Con Condenser Side Garnish - LH	11	1	PCS	124.40	124.40
37	Front Headlamp H/W Bulb Sensor - RH	11	1	PCS	403.10	403.10
38	Front Air-Con Fan Cowling	cre	1	PCS	212.40	212.40
39	Front Air-Con Fan Blade	11	1	PCS	163.40	163.40
40	Front Air-Con Fan Motor	11	1	PCS	399.40	399.40
41	Front Radiator	sent/tw	1	PCS	1,440.40	1,440.40
42	Front Radiator Fan Cowling	11	1	PCS	212.40	212.40
43	Front Radiator Fan Blade	11	1	PCS	163.40	163.40
44	Front Radiator Fan Motor	11	1	PCS	399.40	399.40
45	Front Radiator Spare Tank - RH	11	1	PCS	243.10	243.10
46	Front Radiator Spare Tank Top Hose - RH	11	1	PCS	69.40	69.40
47	Rear Boot	11	1	PCS	1,806.20	1,806.20
48	Rear Boot Lock	20/shed	1	PCS	509.40	509.40
49	Rear Boot Lock Catch	11	1	PCS	65.90	65.90
50	Rear Boot S/Absorber	11	2	PCS	399.40	398.40
51	Rear Boot Rubber	tw	1	PCS	398.40	398.40
52	Rear Boot Inner Cover Board	11	1	PCS	780.10	780.10
53	Rear Spare Tyre Panel	cramped/buc	1	PCS	866.40	866.40
54	Rear Spare Tyre Panel Top Cover Board	wogel	1	PCS	310.40	310.40
55	Rear Spare Tyre Centre Tool Sponge	to.n	1	PCS	544.10	544.10
56	Rear Spare Tyre Side Tray Sponge	11	2	PCS	210.40	420.80
57	Rear Fender Inner Side Garnish	2e/to.n	2	PCS	712.10	1,424.20
58	Rear End Panel	2.05.20	1	PCS	517.90	517.90
59	Rear End Panel Top Garnish	2.5	1	PCS	349.10	349.10
60	Rear Bumper	2.5	1	PCS	686.40	686.40
61	Rear Bumper Reflector Cover	cu	2	PCS	110.20	220.40
62	Rear Bumper Side Retainer	sent	2	PCS	103.10	206.20
63	Rear Bumper Lower Pad	2.5	1	PCS	545.10	545.10
64	Rear Bumper Reinforcement	2.5	1	PCS	394.70	394.70
65	Rear Bumper Lower Pad Lock Clip	11	6	PCS	12.90	77.40
66	Rear Bumper Towing Cover	to.n	1	PCS	66.30	66.30
67	Rear Bumper Side Under Cover - LH	11	1	PCS	110.20	110.20
68	Rear Bumper Side Under Cover - RH	11	1	PCS	110.20	110.20
69	Rear Bumper Lower Clip	11	10	PCS	12.90	129.00
70	Rear Exhaust Silencer	20/tw	1	PCS	1,020.80	1,020.80
71	Rear Exhaust Silencer Mounting	11	2	PCS	46.20	92.40
72	Rear Exhaust Silencer Top Cover Aluminium Plate	sent 290	1	PCS	394.10	394.10
73	Rear Smart Sensor	cre	1	PCS	304.90	304.90

299.10

545.10

343.10

45.00

188.20

TOTAL A :	33,929.30
DISCOUNT 25% :	8,482.33
SUB TOTAL :	25,446.98

SPECIAL NET

1	Front Number Plate	5.00	1	PCS	40.00	40.00
2	Rear Bumper Sensor	shed	1	SET	300.00	300.00
3	Rear Windscreen Gum	11	1	PCS	80.00	80.00

TOTAL B :	420.00
------------------	---------------

FOCUS AUTO PTE LTD
 NO. 1 KAKI BUKIT AVENUE 6 #02-48/50
 AUTOBAY @ KAKI BUKIT SINGAPORE 417883
TEL: 6886 9097 FAX: 6844 4625 Email: claims@focusauto.com.sg

LABOUR CHARGES

	SS	SS
1 Panel Beating		2,600.00
2 Check Wiring and Diagnosis Check	2000	250.00
3 Rust Proofing	50	
4 To Remove & Refix Rear Windscreen	100	160.00
5 To Remove & Replace Air-Con Condenser and Change Gas	11 X	160.00
6 To Remove & Refix Rear Seal and Up-Hole Set Up	100	160.00
7 To Remove & Replace Rear Exhaust	100	160.00
8 To Remove & Replace Rear Bumper Sensor	✓	80.00
9 To Spray Painting	50	80.00
	✓	1,600.00
TOTAL C :		5,250.00
GRAND TOTAL :		31,116.98

FOR FOCUS AUTO PTE LTD


Jenny Koh
Claims Executive
MP: 8139 9800

 AUTHORISE SIGNATURE

LKIC Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

P-24191-4
 252
 P-18143-SR
 S-N-240
 L-4080
 22463-SR
 202