

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 29/03/2022

30/03/2022

TPAXA

Xiao Tony

Estimated repair cost for vehicle no: GBB6377P TOYOTA DYNA 150 MANUAL 3 SEATER

CHASSIS: JTFAT35Y50K200850 (2009)

S/N	Qty	Items	U/price	Amount
1	1	FRONT BUMPER <i>Distorted</i>	\$698.10	\$698.10 ✓
2	2	FRONT BUMPER BRACKET <i>LH Bent</i>	\$121.10	\$242.20 121.10
3	1	FRONT CHASSIS CROSSMEMBER <i>Repair</i>	\$698.20	\$698.20 ✓
4	1	FRONT GRILLE <i>Cracked</i>	\$471.20	\$471.20 ✓
5	1	FRONT GRILLE LOGO <i>new</i>	\$65.30	\$65.30 ✓
6	2	FRONT HEADLAMP <i>LH cracked</i>	\$556.20	\$1,112.40 556.20
7	1	LH FRONT CORNER PANEL GARNISH <i>Distorted</i>	\$245.60	\$245.60 ✓
8	1	FRONT PANEL <i>Distorted</i>	\$1,015.00	\$1,015.00 ✓
9	1	FRONT PANEL EMBLEM DYNA <i>new</i>	\$58.60	\$58.60 ✓
10	1	FRONT PANEL CENTER PROTECTOR <i>new</i>	\$321.10	\$321.10 ✓
11	1	FRONT PANEL PROTECTOR LH <i>new</i>	\$148.10	\$148.10 ✓
12	1	FRONT WIPER PANEL <i>Repair</i>	\$386.90	\$386.90 ✓
13	1	LH FRONT MIRROR ARM <i>new</i>	\$322.40	\$322.40 ✓
14	1	LH FRONT MIRROR ARM COVER <i>new</i>	\$96.10	\$96.10 ✓
15	1	LH FRONT SQUARE MIRROR <i>Missing</i>	\$322.50	\$322.50 ✓
16	1	LH FRONT ROUND MIRROR	\$112.30	\$112.30 ✓
17	1	LH STEP GARNISH <i>new</i>	\$321.60	\$321.60 ✓
18	1	LH FRONT DOOR <i>Repair</i>	\$1,359.40	\$1,359.40 ✓
19	2	LH FRONT DOOR HINGE <i>new</i>	\$112.10	\$224.20 ✓
20	1	LH FRONT DOOR STOPPER <i>new</i>	\$78.40	\$78.40 ✓
21	1	LH FRONT DOOR WEATHER STRIPE <i>new</i>	\$212.30	\$212.30 ✓
22	1	AIR CON BLOWER MOTOR <i>Cracked</i>	\$986.10	\$986.10 ✓
23	1	AIR CON COOLING COIL <i>Cracked</i>	\$1,310.20	\$1,310.20 ✓

7171.50
5378.62

TOTAL : \$10,808.20
LESS 25 % \$2,702.05
SUB-TOTAL : \$8,106.15

6849.10

5136.82

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	FRONT GRILLE CLIPS <i>new</i>	\$80.00	\$80.00 20
2	1	LH FRONT CORNER PANEL GARNISH CLIPS <i>x1ea</i>	\$60.00	\$60.00 20
3	1	FRONT NUMBER PLATE WITH CASING <i>missing</i>	\$60.00	\$60.00 ✓
4	1	AIR CON GAS <i>new</i>	\$120.00	\$120.00 50

150

TOTAL: \$320.00

TOTAL PARTS \$8,426.15

Labour charges

1	LABOUR FOR PANEL BEATING	\$1,000.00 150
2	LABOUR FOR SPRAYPAINTING	\$900.00 800
3	WIRING CHECK	\$80.00 30
4	TO APPLY TUFF COATING/RUST PROOF ACCIDENT AREAS	\$300.00 80 120
5	LABOUR FOR REMOVE & REFIX FRONT WINDSCREEN GLASS <i>2470</i>	\$150.00 120
6	LABOUR FOR REMOVE & REFIX FRONT DASHBOARD	\$200.00 180
7	LABOUR FOR REMOVE & RENEW AIR CON BLOWER MOTOR / COOLING COIL TO VACCUM & TOP UP AIR CON GAS	\$150.00 120
8	LABOUR FOR REMOVE & TRANSFER LH FRONT DOOR FITTING	\$150.00 X

Subtotal :- \$2,930.00

Adrian Ly
1/5 01/04/22. Total:- \$11,356.15

06 days

Supplementary: 1234.5

total: 8993.12

4/5: 7.2K

total: 8991.32

4/5: 7.2K

7.2K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

Blk 1 Kaki Bukit Ave 6

01/04/2022

01-43

Singapore 417883

Accident date : 29/03/2022

Estimated repair cost for vehicle no: GBB6377P TOYOTA DYNA 150 MANUAL 3 SEATER

CHASSIS: JTFAT35Y50K200850 (2009)

SUPPLEMENTARY

S/N	Qty	Items	U/price	Amount
1	1	AIR CON CONDENSER <i>Best</i>	\$1,025.30	\$1,025.30 756
2	2	FAN / MOTOR / COWLING <i>amb</i>	\$985.60	\$985.60 550
3	1	AIR CON PIPE (FROM DRYER TO CONDENSER) <i>Best</i>	\$259.50	\$259.50 185
4	1	LH FRONT SAFETY BAR <i>Best</i>	\$341.60	\$341.60 145

TOTAL : \$2,612.00

LESS 25 % \$653.00

SUB-TOTAL : \$1,959.00

1646

Supplementary : 1234.50