

ASS. REC. BY:

REF:

LPC / 22003048/KC

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

100m

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLH 5529A

Yr Regn:

11, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda HRV

c.c

1496

Colour

M.P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

70360

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JHMRU1810GX 201194

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

30/3/22

D.O.A.

1/4/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2/4 11:15 @ 21501 Center

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + RS. SI

Fuel

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$)

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech Invs (\$)

☐

: Weekend (\$)

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : ZHENG KENG ENGINEERING & CONSTRUCTION
 20 SENOKO CRESCENT

Estimate No: MC1902568

Date: 31 Mar 2022

Policy No: 2021-V0102378-VDP-

Veh Reg No: SLH5529A

Make/Model: HONDA HRV 1.5 DX
 CVT

SINGAPORE 758274

TEL: 67549489 MS ONG

ATTN:

Your Ref No: -

Claim Type: Third Party - LONPAC

Accident Date: 30/03/2022

TP Veh Reg No: SGV5067B

*Not Notified
 L1 Sur @ 2150/hr
 Resurvey After Painting
 4 days*

Estimate Repair Cost to Vehicle No :SLH5529A

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 REAR WINDSCREEN MOULDING SET	1 PC	Mc 128.40	✓
2 TAILGATE	1 PC	B 741.20	✓
3 TAILGATE LOGO HR-V	1 PC	mc 43.20	✓
4 TAILGATE LOGO I-VTEC	1 PC	mc 29.40	✓
5 TAILGATE LOCK	1 PC	R 96.60	X
6 TAILGATE LOCK CATCH	1 PC	R 36.20	X
7 TAILGATE RUBBER	1 PC	Sn 96.80	X
8 REAR BUMPER (GLOSSY)	1 PC	Bu 829.40	✓
9 REAR BUMPER CLIPS	8 PC	mc 28.00	✓
10 REAR SMART BUZZER	1 PC	Sn 80.10	X
11 REAR KEYLESS ANTENNA	1 PC	Sn 58.10	X
12 REAR END PANEL	1 PC	R 538.20	X
13 REAR END PANEL GARNISH	1 PC	Sn 66.60	X
14 REAR FLOOR UNDERCOVER	1 PC	Sn 190.20	X
		2,962.40	
	Less 20%	592.48	2,369.92
Special Nett			
15 PARKING SENSOR 4-IN-1 SET	1 PC	short 400.00	320.00
16 NUMBER PLATE	1 PC	Sn 35.00	X
17 INNER SEAL	1 PC	mc 20.00	✓
18 SEALANT	1 PC	mc 40.00	✓
		495.00	495.00
LABOUR			
19 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	15/
20 TO REMOVE & REFIT REAR WINDSCREEN	1 EA	120.00	✓
21 TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	1 PC	60.00	✓
22 TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS.	1 PC	60.00	50/
23 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	30/
24 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD REAR END PANEL. TO KNOCK & REPAIR SPARE TYRE PANEL, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	700.00	400/
25 TO SPRAY TAILGATE, REAR END PANEL, SPARE TYRE PANEL	1 PC	600.00	220/
		1,640.00	1,640.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : ZHENG KENG ENGINEERING & CONSTRUCTION
20 SENOKO CRESCENT

SINGAPORE 758274

TEL: 67549489 MS ONG

ATTN:

Estimate No: MC1902568

Date: 31 Mar 2022

Policy No: 2021-V0102378-VDP-

Veh Reg No: **SLH5529A**

Make/Model: HONDA HRV 1.5 DX
CVT

Your Ref No: -

Claim Type: Third Party

Accident Date: 30/03/2022

TP Veh Reg No: SGV5067B

Estimate Repair Cost to Vehicle No :SLH5529A

Description	Quantity	List Price	Amount
		S\$	S\$
		Total	S\$ 4,504.92
		Add GST @ 7%	315.34
		Total Amount Payable	S\$ 4,820.26

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND EIGHT HUNDRED TWENTY AND CENTS TWENTY SIX ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE