

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : ZHENG KENG ENGINEERING & CONSTRUCTION
20 SENOKO CRESCENT

SINGAPORE 758274

TEL: 67549489 MS ONG

ATTN:

Estimate No: MC1902568

Date: 31 Mar 2022

Policy No: 2021-V0102378-VDP-

Veh Reg No: SLH5529A

Make/Model: HONDA HRV 1.5 DX
CVT

Your Ref No: -

Claim Type: Third Party

Accident Date: 30/03/2022

TP Veh Reg No: SGV5067B

Estimate Repair Cost to Vehicle No :SLH5529A

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 REAR WINDSCREEN MOULDING SET	1 PC	128.40	
2 TAILGATE	1 PC	741.20	
3 TAILGATE LOGO HR-V	1 PC	43.20	
4 TAILGATE LOGO I-VTEC	1 PC	29.40	
5 TAILGATE LOCK	1 PC	96.60	
6 TAILGATE LOCK CATCH	1 PC	36.20	
7 TAILGATE RUBBER	1 PC	96.80	
8 REAR BUMPER (GLOSSY)	1 PC	829.40	
9 REAR BUMPER CLIPS	8 PC	28.00	
10 REAR SMART BUZZER	1 PC	80.10	
11 REAR KEYLESS ANTENNA	1 PC	58.10	
12 REAR END PANEL	1 PC	538.20	
13 REAR END PANEL GARNISH	1 PC	66.60	
14 REAR FLOOR UNDERCOVER	1 PC	190.20	
		2,962.40	
	Less 20%	592.48	2,369.92
Special Nett			
15 PARKING SENSOR 4-IN-1 SET	1 PC	400.00	
16 NUMBER PLATE	1 PC	35.00	
17 INNER SEAL	1 PC	20.00	
18 SEALANT	1 PC	40.00	
		495.00	495.00
LABOUR			
19 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	
20 TO REMOVE & REFIT REAR WINDSCREEN	1 EA	120.00	
21 TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	1 PC	60.00	
22 TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS.	1 PC	60.00	
23 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	
24 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD REAR END PANEL. TO KNOCK & REPAIR SPARE TYRE PANEL, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	700.00	
25 TO SPRAY TAILGATE, REAR END PANEL, SPARE TYRE PANEL	1 PC	600.00	
		1,640.00	1,640.00

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : ZHENG KENG ENGINEERING & CONSTRUCTION
20 SENOKO CRESCENT

SINGAPORE 758274

TEL: 67549489 MS ONG

ATTN:

Estimate No: MC1902568

Date: 31 Mar 2022

Policy No: 2021-V0102378-VDP-

Veh Reg No: SLH5529A

Make/Model: HONDA HRV 1.5 DX
CVT

Your Ref No: -

Claim Type: Third Party

Accident Date: 30/03/2022

TP Veh Reg No: SGV5067B

Estimate Repair Cost to Vehicle No :SLH5529A


Description	Quantity	List Price S\$	Amount S\$
Total			S\$ 4,504.92
Add GST @ 7%			315.34
Total Amount Payable			S\$ 4,820.26

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND EIGHT HUNDRED TWENTY AND CENTS TWENTY SIX ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE