

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

7300

ANANDA WONG MAN JIE

BLK 476B CHOA CHU KANG AVE 5 #15-27

SINGAPORE 682476

Contact : 91787103

TAX INVOICE

Repair Code : CLM15495

Date in : 31/03/2022

Vehicle Num. : SMK164Z

Model : HONDA JAZZ 1.5 CVT

Chassis/Eng# : JHMGK5850JX204242/L15B33111909

Parts and Labour Assessment

Description of part	Qty	Unit Price	Amount
REAR BUMPER / <i>De</i>	1	551.50	551.50 ✓
REAR BUMPER GRILLE COVER L/R = <i>YBR</i>	2	48.10	96.20 ✓
REAR BUMPER SIDE RETAINER L/R	2	11.50	23.00 ✓
REAR END PANEL / <i>Buc</i>	1	505.40	456.5 505.40 341.6
REAR END PANEL ANTENNA SENSOR = <i>Y CFA</i>	1	107.40	107.40 ✓
REAR END PANEL BUZZLE SENSOR	1	98.40	98.40 ✓
REAR END PANEL INNER TOP GARNISH / <i>ee</i>	1	60.80	60.80 ✓
REAR FENDER INNER TRIM GARNISH L/R / <i>Re</i>	2	199.70	399.40 ✓
REAR FLOOR PANEL <i>X Repair</i>	1	683.30	683.30
REAR FLOOR PANEL SPONGE TRAY / <i>ee</i>	1	127.30	127.30 ✓
REAR FLOOR PANEL TOP BOARD COVER / <i>ee</i>	1	189.90	189.90 ✓
REAR FLOOR SIDE PANEL LH / <i>Buc</i>	1	379.20	379.20 ✓
REAR LH FENDER <i>Repair</i> X	1	588.30	588.30
REAR LH FENDER GLASS MOULDING X <i>NN</i>	1	56.90	56.90
REAR LH FENDER INNER AIR VENT / <i>Yee</i>	1	38.50	38.50 ✓
REAR LH FENDER INNER LOWER SHIELD / <i>Yee</i>	1	35.70	35.70 ✓
REAR LH FENDER INNER SHIELD X <i>NN</i>	1	149.80	149.80
REAR LH TAILLAMP PANEL / <i>Buc</i>	1	108.90	108.90 ✓

*** This is a computer-generated document which requires no signature.***

AutoHub
Sukit Ave 2
#01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

ANANDA WONG MAN JIE
BLK 476B CHOA CHU KANG AVE 5 #15-27
SINGAPORE 682476

Contact : 91787103

TAX INVOICE

Repair Code : CLM15495

Date in : 31/03/2022

Vehicle Num. : SMK164Z

Model : HONDA JAZZ 1.5 CVT

Chassis/Eng# : JHMGK5850JX204242/L15B33111909

REAR TAILGATE	1	1071.10	846	1,071.10	779.2
REAR TAILGATE 'RS' EMBLEM	1	89.40		89.40	45.4
REAR TAILGATE DAMPER L/R	2	106.80		213.60	
REAR TAILGATE HINGES L/R	2	33.20		66.40	
REAR TAILGATE INNER PULL HANDLE	1	18.50		18.50	✓
REAR TAILGATE INNER RUBBER SIDE GUIDE STOPPER L/R	2	15.50		31.00	
REAR TAILGATE INNER TRIM BOARD	1	63.70		63.70	✓
REAR TAILGATE MECHANISM LOCK	1	78.90		78.90	✓
REAR TAILGATE NUMBER PLATE LAMP L/R	2	45.00		90.00	✓
REAR TAILGATE OUTER CHROME HANDLE	1	133.40		133.40	✓
REAR TAILGATE REFLECTOR L/R	2	125.00		250.00	✓
REAR TAILGATE WEATHER STRIP	1	92.30		92.30	✓
REAR TAILGATE WINDSCREEN	1	1025.60		1,025.60	✓
REAR TAILGATE WINDSCREEN MOULDING	1	224.70		224.70	98.5
REAR TAILGATE WIPER ARM	1	58.20		58.20	✓
REAR TAILGATE WIPER ARM COVER	1	12.40		12.40	✓
REAR TAILGATE WIPER BLADE	1	69.40		69.40	26
REAR TAILGATE WIPER MOTOR	1	355.40		355.40	111.6

*** This is a computer-generated document which requires no signature.***

AutoHub
 #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

ANANDA WONG MAN JIE
 BLK 476B CHOA CHU KANG AVE 5 #15-27
 SINGAPORE 682476

Contact : 91787103

TAX INVOICE

Repair Code : CLM15495

Date in : 31/03/2022

Vehicle Num. : SMK164Z

Model : HONDA JAZZ 1.5 CVT

Chassis/Eng# : JHMGK5850JX204242/L15B33111909

REAR TAILLAMP L/R	2	268.90	537.80	✓
Subtotal before discount		6161	8,681.70	5979.3
Percentage discount 20%			1,736.34	
Sub-total 1		4928.8	6,945.36	4783.44
REAR BUMPER CLIPS - SET	1	50.00	50.00	30
REAR BUMPER REVERSE SENSOR (4 EYES) - SET	1	450.00	200 450.00	200
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	50.00	50.00	20
REAR FENDER INNER TRIM BOARD CLIPS L/R - SET	2	50.00	100.00	40
REAR FLOOR PANEL INSULATOR MAT	1	300.00	300.00	X
REAR LH FENDER GLASS SEALANT	1	60.00	60.00	X
REAR LH FENDER INNER SHIELD CLIPS - SET	1	50.00	50.00	20
REAR TAILGATE CAMERA	1	800.00	280 800.00	280
REAR TAILGATE INNER TRIM BOARD CLIPS - SET	1	50.00	50.00	20
REAR TAILGATE NUMBER PLATE	1	25.00	25.00	35
REAR TAILGATE NUMBER PLATE HOLDER	1	50.00	50.00	35
REAR TAILGATE OUTER CHROME HANDLE CLIPS - SET	1	40.00	40.00	10
REAR TAILGATE VIDEO RECORDER	1	980.00	380 980.00	380
REAR TAILGATE WINDSCREEN SOLAR FILM	1	250.00	250.00	200

*** This is a computer-generated document which requires no signature.***

Jit AutoHub
 Bukit Ave 2
 #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

ANANDA WONG MAN JIE
 BLK 476B CHOA CHU KANG AVE 5 #15-27
 SINGAPORE 682476

Contact : 91787103

TAX INVOICE

Repair Code : CLM15495

Date in : 31/03/2022

Vehicle Num. : SMK164Z

Model : HONDA JAZZ 1.5 CVT

Chassis/Eng# : JHMGK5850JX204242/L15B33111909

REAR TAILGATE WINDSCREEN SEALANT	1	80.00	80.00	40
REAR TAILLAMP CLIPS L/R - SET	2	30.00	60.00	10
Subtotal before discount			3,395.00	1285
Percentage discount 0%			0.00	
Sub-total 2			3,395.00	
Parts-total			10,340.36	

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

80.00 40

To remove, reinstall tailgate windscreen

150.00 120

To remove, reinstall petrol tank. (to FR)

nn 80.00 X

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

120.00 60

To send vehicle for cleaning, shampoo, upholstery and cushion seat.

250.00 180

To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.

1200 1,400.00

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

1200 1,900.00

To apply anti-rust chemical on repaired and replaced panel.

120.00 60

To remove, reinstall tailgate mechanism and check for function

80.00 40

Labour Total

2900 4,180.00

Parts & Labour Total

14,520.36

9113.8

8000.44

7300

~~20%: 7150~~

*** This is a computer-generated document which requires no signature.***

page 4

8 Days.

C/S

After repair photos

Emo At 4

LINK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: