



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2303902

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 19/06/2023
Reference CC6/CTI22003056/Apa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SMQ 799K
Insured Veh. SKM 1219G
Claim No. SNM22D202261/C02
Policy No. DMPCSNW00013812200
Accident Date 01/04/2022
Inspection Date 01/04/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22003056/Apa3q2 Date: 19/06/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKM 1219G	Veh. Inspected	SMQ 799K	
Policy No.	DMPCSNW00013812200	Coverage (\$)	0.00	
Claim No.	SNM22D202261/C02	Excess (\$)	0.00	
Assign From		Assign Date	01/04/2022	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. X5	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WBALS020X00U16428	Colour	BLACK	
Odometer	81622 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	315/35 R20	PIRELLI	6 mm	
L/H Front Tyre	315/35 R20	PIRELLI	6 mm	
R/H Rear Tyre	315/35 R20	PIRELLI	6 mm	
L/H Rear Tyre	315/35 R20	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/04/2022	Inspection Date	01/04/2022	
Survey held at	ADVANCE AUTO GARAGE 23 KAKI BUKIT AVENUE 4, #04-01 VICOM KAKI BUKIT INSPECTION CENTER, SINGAPORE 415933.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMQ 799K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DISTORTED	1,758.00	1,758.00
2	REAR BUMPER SIDE HOLDER @\$158.00	DAMAGED	316.00	316.00
1	REAR BUMPER REINFORCEMENT	BENT	796.00	796.00
1	REAR BUMPER CENTRE GUIDE	CRACKED	219.00	219.00
2	REAR BUMPER REFLECTOR @\$75.00	N/S CRACKED	150.00	75.00
1	REAR BUMPER TOW COVER	DEFORMED	38.00	38.00
1	REAR BUMPER LOWER GARNISH	DEFORMED	396.00	396.00
1	REAR BUMPER CHROME MOULDING	NECESSARY	280.00	280.00
4	REVERSE SENSOR @\$265.00	DAMAGED (2 PCS ONLY)	1,060.00	530.00
4	REVERSE SENSOR HOLDER @\$25.00	NECESSARY	100.00	100.00
1	REAR END PANEL	DENTED	1,140.00	1,140.00
1	REAR END PANEL TOP GARNISH	DEFORMED	242.00	242.00
1	REAR END PANEL ANTENNA SENSOR	CRACKED	158.00	158.00
2	TAILLAMP @\$659.00	NOT NECESSARY	1,318.00	-
1	TAILGATE (LOWER)	DEFORMED	1,715.00	1,315.00
1	TAILGATE (LOWER)LOCK	DAMAGED	395.00	395.00
1	TAILGATE (LOWER) TOP TRIM	DEFORMED	268.00	268.00
1	TAILGATE (LOWER)INNER TRIM COVER	DEFORMED	306.00	306.00
1	FLOOR PANEL TOP BOARD	NOT NECESSARY	598.00	-
1	UTILITY STORAGE BOX	DEFORMED	297.00	297.00
2	REAR FENDER INNER TRIM BOARD @\$590.00	NOT NECESSARY	1,180.00	-
1	REAR EXHAUST PIPE	NOT NECESSARY	1,715.00	-
1	REAR EXHAUST PIPE MOUNTING	NOT NECESSARY	42.00	-
1	REAR EXHAUST PIPE HEAT SHIELD	NOT NECESSARY	314.00	-
1	REAR EXHAUST PIPE GASKET	NOT NECESSARY	38.00	-
	LESS 5% DISCOUNT		-	-431.45
			14,839.00	8,197.55
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	60.00	60.00

Report Ref No. CC6/CTI22003056/Apa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	20.00	20.00
1	REAR FENDER INNER TRIM BOARD CLIPS (SN)	NOT NECESSARY	60.00	-
			190.00	130.00
	LABOUR			
	PANEL BEATING.		1,400.00	800.00
	SPRAY PAINTING .		1,400.00	800.00
	WIRING.		100.00	30.00
	TO REMOVE REVERSE SENSOR .		100.00	50.00
	TO REMOVE UPHOLSTERY .		150.00	80.00
	TO SPRAY TUFF COAT.		150.00	80.00
	TO REMOVE REAR CAMERA.	NOT NECESSARY	100.00	-
	TO REMOVE EXHAUST PIPE .	NOT NECESSARY	150.00	-
	TO PERFORM DIAGNOSTIC TEST.		150.00	120.00
			3,700.00	1,960.00
GRAND TOTAL			18,729.00	10,287.55

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			8,200.00
---	--	--	-----------------

Report Ref No. CC6/CTI22003056/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMQ 799K

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMQ 799K

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

