

SMQ799K 2017 Sept.

BMW X5. 1895CC

TP China
Xiao Yang

WBALS020X00U16428

Rear Bumper.	Distorted	1758. -
		50(SN) -
Rear Bumper Clips.	per	
Rear Bumper Side Holder x 02	2nd	158 x 2 = 316. -
Rear Bumper Reinforcement.	2nd	796. -
Rear Bumper Centre Guide.	2nd	219. -
Rear Bumper Reflector x 02	LH 2nd	75 x 2 = 150 75.
Rear Bumper Low Cover.	2nd	38. -
Rear Bumper Lower Garnish.	2nd	396. -
Rear Bumper Chrome Moulding	per	280 -
Reverse Sensor x 04.	2 pieces changed	265 x 4 = 1060 530
Reverse Sensor Holder x 04.	new	25 x 4 = 100. -
Rear End Panel.	Distorted	1140. -
Rear End Panel Sealant.	new	60(SN) -
Rear End Panel Top Garnish.	2nd	242 -
Rear End Panel Top Garnish Clips.	per	20(SN) -
Rear End Panel Antenna Sensor	2nd	158 -

SMQ 799K.

Taillap	x 02	MP	659 x 2 = 1318. +
Tailgate (lower)	Dehd		1715 / 1315
Tailgate (lower) Lock	Dehd		295 -
Tailgate (lower) Top Trim	Dehd		268 -
Tailgate (lower) Inner Trim Cover	Dehd		306. -
Floor Panel Top Board	MP		598. +
Utility Storage Box	Dehd		297 -
Rear Fender Inner Trim Board	x 02	MP	590 x 2 = 1180 +
Rear Fender Inner Trim Board Clips		MP	60 (SN) +
Rear Exhaust Pipe			1715 +
Rear Exhaust Pipe Mounting			42 +
Rear Exhaust Pipe Heat Shield		MP	314. +
Rear Exhaust Pipe Gasket		MP	38. +

8029 S.N.: 110
Km 5/1: 8197.55

SMQ 799K.

Panel Beating

Spray Painting.

Wiring.

To remove reverse sensor

To remove upholstery.

To spray tuff coat. 1960

To remove rear camera.

To remove exhaust pipe.

To perform diagnostic test.

~~1400~~ 800

~~1400~~ 800

~~1000~~ 300

~~1000~~ 500

~~1500~~ 800

~~1500~~ 800

1000 X

1500 X

~~1500~~ 1200

total: 10267.55

L/S: 82K.

06 Days

EST TOTAL: \$18,729.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

8,200
6 days