

SLMS2836 . 2017 March.

Mazda 3 1496 cc

TP Chim
Ceilia.

JMGBN22A8H0145968

Rear Bumper Deformed 1028 ✓

Rear Bumper Clips. ^{new} 30(SN) ✓

Rear Bumper Side Holder x02 ^{new} 38x2 = 76. x

Rear Bumper Tow Cover x02 ^{HP} 18x2 = 36 x

Rear Bumper Reinforcement Dented 498.60 ✓

Rear Bumper Reflector x02 ^{HP} 53x2 = 106. X

Reverse Sensor Damaged 280(~~SN~~) 200(SN)
1526.60 S.N: 230
1221.28

Panel Beating ~~400~~ 200
Spray Painting. ~~400~~ 200 480.

Wiring. ~~50~~ 30

To remove reverse sensor ~~100~~ 50

Total: 1931.28
CPIP)
03 Days.