

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SLH7521H  
 Accident Date : 30-Mar-2022

No. : 06564  
 Date : 31-Mar-2022

Our Ref : 022056 (AIG) / CHAN

PAGE : 1

MOHAMMAD FAIZAL BIN YAHYA  
 BLK 360C ADMIRALTY DRIVE  
 #01-46  
 Singapore 753360

*Not withstanding  
 1/1 Pay @ 3350/-  
 Resurvey After Paint  
 4 days*

ESTIMATED COST OF REPAIR FOR MIT. OUTLANDER SKV5426B

1 pc	Front bumper fascia	Buc	855.00	✓
1 pc	Front o/s bumper arch garnish	Del/Lg	104.00	✓
1 pc	Front O/s bumper side retainer	O.I	16.00	✓
1 pc	Front o/s foglamp cover	Lt	71.00	✓
1 pc	Front o/s bumper outer chrome	Ln	198.00	X
1 pc	Front o/s sport rim	Del	1,152.00	✓
1 pc	Front o/s knuckle arm	Bt	332.00	✓
1 pc	Front o/s knuckle bearing hup	Rt	204.00	✓
1 pc	Front o/s wheel bearing	Ln	143.00	✓
1 pc	Front o/s lower arm	Dil	333.00	✓
1 pc	Front o/s shock absorber	Rt	460.00	✓

3,868.00  
 Less 10% : 386.80

3,481.20

To dismantle and lower front undercarriage

200.00

*180*

To check and adjust wheel alignment

65.00

*60*

To putty and spray replaced parts

500.00

*400*

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

400.00

*300*

Total : S\$ 4,646.20

Singapore Dollars Four Thousand Six Hundred Forty Six and Cents Twenty Only

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer