

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# : SGK6873S

Model:

HONDA JAZZ

Accident Date : 30/3/2022

27/6/2016

Location : JURONG EAST AVE 1

3P: SKQ51K (CHINA TAIPING)

JHMGK58509x203117

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front bumper <i>Del</i>	860.60	495	
2	10 pcs	Front bumper clips <i>new</i>		40.00	✓
3	1 pc	Front bumper enforcement <i>new</i>	182.40	+	
4	1 pc	Front bumper o/s bracket <i>new</i>	28.20	+	
5	1 pc	Front bumper o/s retainer <i>new</i>	20.80	✓	
6	1 pc	Front bumper o/s corner clips <i>new</i>	26.50	+	
7	1 pc	Front bumper o/s fog lamp <i>Del</i>	428.20	225	
8	1 pc	Front bumper o/s fog lamp garnish <i>Del</i>	106.20	75	
9	1 pc	Front o/s head-lamp <i>Del</i>	1,626.80	1392	
10	1 pc	Front o/s wiper tank <i>new</i>	132.40	+	
11	1 pc	Front o/s fender <i>Rep</i>	426.20	+	
12	1 pc	Front o/s fender wheel guard <i>Del</i>	122.60	✓	
13	8 pcs	Front o/s fender wheel guard clips <i>new</i>		32.00	✓
14	1 pc	Front o/s suspension strut	281.20	+	
15	1 pc	Front o/s suspension lower arm	210.20	+	
16	1 pc	Front o/s knuckle	268.40	+	
17	2 pcs	Front o/s wheel bearing <i>new</i>	140.10	+	
		<i>2333.4 SN: 72</i> Sub-Total:	4,860.80	72.00	0.00
		<i>1866.72</i>	25%	0%	10%
		After Less %:	3,645.60	72.00	0.00
		Labour			
1		To remove and replace front o/s damage parts	800.00	300	
2		To spray painting.	600.00	400	
3		To check for alignment	120.00	+	
4		To re-set electrical system.	180.00	+	
5		To check wiring.	80.00	30	
6		To re-seal anti-rust.	80.00	30	
		Sub-Total:	1,860.00		
		Total:	5,577.60		
		After Less 20%:	4,462.08		

Chan

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)

total: 2698.72 Adnan G
L/S: 2.1K. L/S 31/03/22
03 Days



SGK6873S ESTIMATE Pg 1