

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0256/2022/JT
DATE : 30-Mar-22
WIP : 17826

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 1/4/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

OWNER'S NAME : MR LIM KAR HENG DENNIS
ADDRESS : 50 CHO A CHU KANG NORTH
#06-09
SINGAPORE 689527
TELEPHONE : HP +65 96254063
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210027627
VEHICLE NO : SLV 4898 S
MODEL CODE : AUDI A4 2.0 TFSI S TRONIC
MODEL YEAR : 19/3/2021
ENGINE NO : DEM 025395
CHASSIS NO : WAUZZZF45MN000903
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 13-Sep-21
PLACE OF ACCIDENT : 1 GUL CIRCLE

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLV 4898 S

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	X <i>MM</i>
2	TO RENEW REAR WINDSCREEN AND RHS 1/4 GLASS TO FACILITATE THE RENEWAL OF LHS REAR FENDER.	S/N \$	600.00	/
3	TO INSTALL SOLAR FILM FOR AFFECTED GLASSES.	S/N \$	400.00	/
4	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN AND 1/4 GLASS.	S/N \$	200.00	/
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	S/N \$	1,400.00	/
6	TO REMOVE AND REINSTALL REAR SEAT. BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN ATTACH. ETC	S/N \$	1,400.00	/
TOTAL LABOUR CHARGES		:	\$ 4,360.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLV 4898 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 700.00	700 550
8	TO REMOVE AND RENEW RHS REAR WHEEL SUSPENSION ASSY WITH SUBFRAME.	S/N \$ 2,400.00	X NV
9	TO DISMANTLE AND REINSTALL REAR BUMPER. TO RENEW RHS REAR DOOR AND RHS FRONT DOOR. TO CUT OUT AND WELD RHS REAR FENDER, RHS B-PILLAR, RHS SILL PANEL, RHS ROOF CHANNEL, RHS C-PILLAR REINFORCEMENT AND RHS REAR WHEEL HOUSING OUTER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 9,800.00	4500 4500
10	TO RESPRAY RHS REAR FENDER, FUEL CAP, RHS REAR DOOR, RHS FRONT DOOR, HINGES, 2 DOOR HANDLES, RHS B-PILLAR RHS C-PILLAR REINFORCEMENT, RHS SILL PANEL, ROOF CHANEL, DRAIN CHANNEL, DOOR ENTRANCE AND REAR END PANEL FITTING.	5 @ 550 x 550 100 x 2 50 x 2 \$ 7,500.00	2875 3425
11	TO CARRY OUT FIRST MEASUREMENT ON CAR O-LINER.	S/N \$ 800.00	?
12	TO SETUP THE VEHICLE ON CAR O-LINER TO FACILITATE THE REPAIR.	S/N \$ 2,400.00	?
TOTAL LABOUR CHARGES		\$ 23,600.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLV 4898 S

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
13	TO RENEW RHS REAR RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$	520.00	28a
14	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$	384.00	/
TOTAL LABOUR CHARGES		:	<u>\$ 28,864.00</u>	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLV 4898 S - REAR

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	SIDE PANEL FRAME - RH <i>/ bmc</i>	1	\$	3,199.00	
2	REAR WINDSCREEN <i>/</i>	1	\$	1,287.00	
3	QUARTER WINDOW - RH <i>/</i>	1	\$	730.00	
4	PRIMER <i>/</i>	2	\$	44.00	
5	BLIND RIVET STUD <i>/</i>	1	\$	10.00	
6	GROMMET <i>/</i>	1	\$	2.00	
7	FUEL INSERT <i>X NN</i>	1	\$	100.00	
8	C-PILLAR REINFORCEMENT - RH LOWER <i>?</i>	1	\$	220.00	
9	REAR WHEEL HOUSING LINER - RH OUTER <i>?</i>	1	\$	687.00	
10	REAR WHEEL HOUSING LINER - RH REAR <i>X</i>	1	\$	260.00	
11	REAR WHEEL HOUSING LINER ATTACHMENT PARTS <i>X NN</i>	1	\$	149.00	
12	REAR DOOR - RH <i>/ B.S</i>	1	\$	3,431.00	
13	RIVETTED CAP NUT <i>X NN</i>	13	\$	46.00	
14	REAR DOOR OUTER SEAL - RH <i>/</i>	1	\$	229.00	
15	BONDING AGENT <i>/</i>	1	\$	51.00	
16	CLEANING SOLUTION <i>/</i>	1	\$	74.00	
17	APPLICATOR <i>/</i>	1	\$	8.00	
18	REAR DOOR SEALING STRIP <i>X</i>	1	\$	19.00	
19	REAR DOOR ATTACHMENT PARTS <i>X NN</i>	1	\$	943.00	
20	REAR DOOR CATCH - RH <i>?</i>	1	\$	134.00	
SUB TOTAL SPARE PARTS			:	\$ 11,623.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLV 4898 S - REAR

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR DOOR SEAL INNER - RH ?	1	\$	247.00
22	REAR DOOR HINGE HALF UPPER - RH UPPER	1	\$	49.00
23	REAR DOOR HINGE HAVLES - RH UPPER	1	\$	30.00
24	REAR DOOR HINGE HALVES - RH LOWER	1	\$	53.00
25	REAR HINGES HALVES - RH LOWER	1	\$	53.00
26	REAR DOOR HANDLE TRIM PLATE - RH	1	\$	98.00
27	REAR DOOR HANDLE HOUSING - RH	1	\$	9.00
28	REAR DOOR HANDLE COVER - RH	1	\$	7.00
29	REAR DOOR HANDLE SENSOR - RH	1	\$	255.00
30	REAR DOOR HANDLE - RH	1	\$	47.00
31	REAR DOOR HANDLE UNDERLAY - FRONT / END RH	2	\$	8.00
32	REAR DOOR HANDLE MOUNTING - RH ?	1	\$	183.00
33	REAR DOOR WINDOW REGULATOR - RH ?	1	\$	305.00
34	REAR DOOR WINDOW REGULATOR MOTOR - RH ?	1	\$	371.00
35	REAR DOOR CONTROL UNIT ?	1	\$	796.00
36	REAR DOOR WINDOW GUIDE - RH ?	1	\$	501.00
37	REAR DOOR WINDOW GUIDE TRIM STRIP XXXXXX SR (photo)	1	\$	265.00
38	B-PILLAR TRIM - RH TR / TR NBL	1	\$	167.00
39	C-PILLAR TRIM - RH TR / TR ?	1	\$	159.00
40	QUARTER WINDOW GUIDE RAIL - RH ?	1	\$	79.00
SUB TOTAL SPARE PARTS		:	\$	3,682.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLV 4898 S - REAR

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	REAR DOOR WINDOW APERTURE SEAL - RH INNER	X MM	\$ 125.00	
42	REAR DOOR WINDOW SLOT SEAL TRIM STRIP - RH	1 (photo)	\$ 410.00	
43	REAR DOOR WINDOW - RH ?	1	\$ 322.00	
SUB TOTAL SPARE PARTS		:	\$ 857.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLV 4898 S - FRONT

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT DOOR - RH <i>MLC</i>	1	\$	3,431.00	
2	RIVETTED CAP NUT <i>X NN</i>	17	\$	60.00	
3	FRONT DOOR OUTER SEAL - RH <i>MLC</i>	1	\$	229.00	
4	BONDING AGENT <i>X</i>	1	\$	51.00	
5	CLEANING SOLUTION <i>X</i>	1	\$	74.00	
6	APPLICATOR <i>X</i>	1	\$	8.00	
7	FRONT DOOR ATTACHMENT PARTS <i>X</i>	1	\$	1,153.00	
8	FRONT DOOR CATCH - RH <i>X</i>	1	\$	116.00	
9	FRONT DOOR HANDLE TRIM PLATE - DRIVER SIDE <i>?</i>	1	\$	98.00	
10	FRONT DOOR HANDLE COVER - RH <i>?</i>	1	\$	7.00	
11	FRONT DOOR HANDLE SENSOR - RH <i>X NN</i>	1	\$	255.00	
12	FRONT DOOR HANDLE - RH <i>CPA</i>	1	\$	47.00	
13	FRONT DOOR HANDLE UNDERLAY - FRONT / END RH <i>?</i>	2	\$	8.00	
14	FRONT DOOR MOUNTING BAR - DRIVER SIDE <i>?</i>	1	\$	183.00	
15	FRONT DOOR HOUSING LOCK CYLINDER - DRIVER SIDE <i>?</i>	1	\$	649.00	
16	FRONT DOOR WINDOW REGULATOR - RH <i>X NN</i>	1	\$	305.00	
17	FRONT DOOR WINDOW GUIDE TRIM STRIP - RH <i>SCR (part 2)</i>	1	\$	287.00	
18	B-PILLAR TRIM - RH <i>MLC</i>	1	\$	256.00	
19	FRONT DOOR WINDOW SLOT SEAL TRIM STRIP - RH <i>Cut</i>	1	\$	344.00	
20	TYRE PRESSURE DATA PLATE <i>MLC</i>	1	\$	42.00	
SUB TOTAL SPARE PARTS		:	\$	7,603.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLV 4898 S - FRONT

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR DOOR LOCK - RH ?	1	\$	630.00
22	REAR DOOR STRIKER ?	1	\$	77.00
23	FRONT DOOR LOCK - DRIVER SIDE ?	1	\$	691.00
24	REAR DOOR LOCK STRIKER ?	1	\$	77.00
25	ALUMINIUM RIM - <i>scr</i>	1	\$	1,889.00
26	RUBBER VALVE - <i>mc</i>	1	\$	4.00
27	SUBFRAME SUPPORT X	1	\$	3,643.00
28	WISHBONE ALUMINIUM - LOWER X	1	\$	963.00
29	WISHBONE - RH UPPER X	1	\$	624.00
30	WISHBONE - RH FRONT X	1	\$	137.00
31	WISHBONE - RH REAR X	1	\$	501.00
32	TRACK ROD - RH REAR X	1	\$	188.00
33	REAR WHEEL BEARING HOUSING - RH X	1	\$	1,097.00
34	REAR BEARING WHEELHUB X	1	\$	723.00
35	GAS SHOCK ABSORBER X	1	\$	332.00
36	COUPLING ROD X	1	\$	94.00
37	ANTI-ROLL BAR X	1	\$	456.00
38	DOOR TRIM PANEL ?	1	\$	328.00
39	DOOR WIRING SET - RH ?	1	\$	587.00
40	STONE CHIP / <i>mc</i>	S/N	\$	180.00
SUB TOTAL SPARE PARTS		:	\$	13,221.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLV 4898 S - FRONT

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	METAL FILLER POWDER	S/N	\$ 280.00	
22	ARYLIC SEALANT	S/N	\$ 180.00	
23	CAVITY WAX	S/N	\$ 140.00	
24	1/4 GLASS SEALANT	S/N	\$ 100.00	
25	REAR WINDSCRREN SEALANT	S/N	\$ 200.00	
26	SUNDRIES		\$ 600.00	
TOTAL SPARE PARTS(FRONT & REAR)		:	\$ 38,486.00	
TOTAL LABOUR CHARGES		:	\$ 28,864.00	
GRAND TOTAL		:	\$ 67,350.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Ano Qianf
01/4/2022

Not Authorised.

Excess: TBA

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

before part photos.

15 Days.

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT