

AlGAsia Insured's Veh No : SMX2267D
 Date of Accident : 01 April 2022

Not Approved
4/4/22
2/s #2350
4 days.
Whip the #the repair

Mr Mohammad Firdaus Bin Nor Halis

Date : 02 April 2022

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365

Tel : 68585151 (24 Hours) Fax 68580877

GST Regn. No. : M2-8922054-2

Acknowledged by Repairer

Signature:

Date:

Estimate To Repair SJN9967J - Toyota Corolla Altis 1.6

Chassis No : MR053ZEE106138354

req. LKK - marks

04/04/2022 0900

S/No	Quantity	Description	Amount
LIST ITEMS			
01	1 pc	rear bumper <i>DLS</i>	\$ 586.50 <i>525.10</i>
02	2 ps	rear bumper side retainer - front @ \$104.00 <i>11</i>	\$ 208.00 <i>X</i>
03	2 ps	rear bumper side retainer - rear @ \$104.00 <i>11</i>	\$ 208.00 <i>X</i>
04	10 ps	rear bumper clips @ \$5.00 <i>rec</i>	\$ 50.00 <i>///</i>
05	1 pc	rear bumper sponge <i>win</i>	\$ 112.00 <i>///</i>
06	1 pc	rear bumper end panel bracket <i>1/s 10</i>	\$ 85.00 <i>///</i>
07	1 pc	rear end panel <i>10</i>	\$ 581.20 <i>///</i>
08	1 pc	rear end panel top garnish <i>svc</i>	\$ 229.60 <i>X</i>
09	1 pc	bootlid <i>R</i>	\$ 755.50 <i>X</i>
10	1 pc	boot lid weatherstrip <i>11</i>	\$ 166.40 <i>X</i>
11	1 pc	n/s rear boot lid lamp <i>11</i>	\$ 331.80 <i>X</i>
12	1 pc	n/s rear taillamp <i>CNO 360.10</i>	\$ 568.00 <i>///</i>
13	1 pc	bootlid emblem badge <i>svc</i>	\$ 43.20 <i>X</i>
14	1 pc	bootlid emblem 1.6 badge <i>svc</i>	\$ 55.00 <i>X</i>
15	1 pc	bootlid emblem corolla altis badge <i>svc</i>	\$ 56.80 <i>X</i>
Less 25 %			\$ 4,037.00
			\$ 1,009.25
			\$ 3,027.75
SPECIAL NETT ITEMS			
16	1 set	rear bumper parking sensor <i>shorted</i>	\$ 300.00 <i>200</i>
			\$ 300.00
LABOUR & MISC. CHARGES			
01		To transfer of bootlid fittings, attachments and perform water seepage test.	\$ 120.00 <i>X</i>
02		To reinstall of rear bumper parking sensor.	\$ 80.00 <i>50</i>
03		To rust-proofing of the affected areas.	\$ 200.00 <i>30</i>
04		To check electrical lighting concerned.	\$ 60.00 <i>20</i>
05		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 800.00 <i>680</i>
06		Putty and spray painting of the affected portion.	\$ 800.00 <i>700</i>
			\$ 2,060.00
Total			\$ 5,387.75

p-1713.4
252
1285.05
200 2965.05
480