



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : ODVehicle No. : YQ1684JMake & Model : ISUZU NPR85Year of Manufacture : 2019Chassis No. : JAANPR85HK7100661Ins Company : AW

Engine No. : _____

Excess : _____

Policy No. : _____

Date of Accident : 15/03/2022

Time of Accident : _____

Suggested Days of Repair : _____

In-house Vehicle Assessor**Repair Estimates**Case Owner : PATRICK

Signature : _____

Parts (a) Cost / List Price Items \$ -

Plus/Less 10% \$ -

Total of Cost / List \$ -

(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ -

Total Parts Cost (Appendix A) \$ -

Labour (Appendix B) \$ 2,850.00

Total Repair Cost \$ 2,850.00

Contact No
Frt Counter OperationBrenda Tel: 63837730 email: brendang@sparkcarcare.com
Rohani tel: 63837890 email: rohanim@sparkcarcare.com**Back-end Operation**Ngo Toh Wee Tel: 63837656 email: ngotw@sparkcarcare.com
Patrick Tel: 63837441 email: patricktia@sparkcarcare.com

*Not within
Recovery B4 gain*

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
 Company : LKK
 Survey conducted on : 4/4/22 at _____

Remarks By Surveyor(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.(b) Recommended Days of Repair : 05 day(s)(c) Resurvey : Required / Not Required Required(d) Excess : \$ 1500k(e) Signature of surveyor : Pc Date: 4/4/22

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62815767

Spare Parts

Vehicle No : YQ1684J Case Owner : PATRICK

Make & Model : ISUZU NPR85 Year Manufacture : 2019

Chassis No : JAANPR85HK7100661 Engine No : 0

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : OD

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposit Surveyor
1	FRT BUMPER	CM 1					✓
2	RH BUMPER BRACKET	R 1					✓
3	RADIATOR GRILLE	CM 1					✓
4	RADIATOR GRILLE BASE	1					✓
5	FRT CENTER PANEL	R 1					✓
6	FRT CENTER PANEL RUBBER SEAL	R 1					✓
7	ISUZU EMBLEM	R 1					✓
8	RH LOWER STEP GARNISH	R 1					✓
9	AIR CON BLOWER MOTOR ASSY	1					X
10	AIR CON COOLING COIL ASSY	1					X
11	FRT 100 PLUS STICKER(BUMPER,CTR PANEL,GRILLE)	1	(Induct)				?
12	0	1					
13	0	1					
14	0	1					
15	0	1					
16	0	1					
17	0	1					
18	0	1					
19	0	1					
20	0	1					
21	0	1					
22	0	1					
23	0	1					
24	0	1					
25	0	1					
26	0	1					
27	0	1					
28	0	1					
29	0	1					
30	0	1					

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

24/03/2022

2:38 PM

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax: 62815767

Vehicle No. : YQ1684J
Make & Model : ISUZU NPR85

Case Owner	:	<u>PATRICK</u>
Year of Manufacture	:	<u>2019</u>

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.