

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : ODVehicle No. : YQ1684JMake & Model : ISUZU NPR85Year of Manufacture : 2019Chassis No. : JAANPR85HK7100661Ins Company : AW

Engine No. : _____

Excess : _____

Policy No. : _____

Date of Accident : 15/03/2022

Time of Accident : _____

Suggested Days of Repair : _____

In-house Vehicle Assessor

Repair EstimatesCase Owner : PATRICK

Signature : _____

Parts (a) Cost / List Price Items \$ -

Contact No

Plus/Less 10% \$ -

Frt Counter Operation

Total of Cost / List \$ -

Brenda Tel: 63837730 email: brendang@sparkcarcare.com

Rohani tel: 63837890 email: rohanim@sparkcarcare.com

(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

Back-end Operation

Ngo Toh Wee Tel: 63837656 email: ngotw@sparkcarcare.com

Patrick Tel: 63837441 email: patricktia@sparkcarcare.com

(c) Special Nett Items \$ -

Total Parts Cost (Appendix A) \$ -

Labour (Appendix B) \$ 2,850.00

Total Repair Cost \$ 2,850.00

The above total will be subjected to 7% G.S.T.

Not Notarized
Return B4pam
\$3794.00

Name of Surveyor : KennethCompany : LKKSurvey conducted on : 4/4/22 at _____

Spare Parts

Vehicle No : YQ1684J Case Owner : PATRICK
Make & Model : ISUZU NPR85 Year Manufacture : 2019
Chassis No : JAANPR85HK7100661 Engine No : 0
Sales Order : _____ Supplier : _____
Order By : _____ Type of Claim : OD

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposit Surveyor
1	FRT BUMPER	CM 1	370				✓
2	RH BUMPER BRACKET	R 1	90				✓
3	RADIATOR GRILLE	CM 1	300				✓
4	RADIATOR GRILLE BASE	Tn 1					X
5	FRT CENTER PANEL	R 1	500				✓
6	FRT CENTER PANEL RUBBER SEAL	Rn 1	30				✓
7	ISUZU EMBLEM	Rn 1	95				✓
8	RH LOWER STEP GARNISH	Rn 1	95				✓
9	AIR CON BLOWER MOTOR ASSY	In 1					✓
10	AIR CON COOLING COIL ASSY	In 1					X
11	FRT 100 PLUS STICKER(BUMPER,CTR PANEL,GRILLE)	? 1	(Induct)				X
12	0	1					?
13	0	1					
14	0	1					
15	0	1					
16	0	1					
17	0	1					
18	0	1					
19	0	1					
20	0	1					
21	0	1					
22	0	1					
23	0	1					
24	0	1					
25	0	1					
26	0	1					
27	0	1					
28	0	1					
29	0	1					
30	0	1					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

