

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lump Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Date / Time

Action / Instruction

Dup 13K.

Veh No:

Yr Regn:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make:

Colour:

Sp Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) \$ + RS. \$ SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I.: (\$

TOTAL



1/2/4/22 hour 6.4
1/5 \$ 9700 insured Alan.

Hsiao Tony

Not Authorized
Lue

4/4/22

1/5 \$9700/
5 days.

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

VEHICLE No: SLM 3115Y

1PC	FRONT BUMPER	Dis	1069.50	\$1,866.00	/
1PC	FRONT BUMPER LOGO	neu	102.00	\$105.00	/
1PC	FRONT BUMPER SIDE RETAINER O/S	one	66.00	\$195.00	/
1PC	FRONT BUMPER FOG LAMP O/S	one	355.00	\$485.00	/
1PC	FRONT BUMPER FOG LAMP COVER O/S	De	162.00	\$380.00	/
1PC	FRONT BUMPER PDC SENSOR O/S	Shorted	184.00	\$225.00	/
1SET	FRONT BUMPER CLIPS	neu		\$60.00	/
1PC	FRONT BUMPER REINFORCEMENT	11		\$619.00	x
1PC	FRONT BUMPER SPONGE	Torn	108.00	\$208.00	/
1PC	FRONT BUMPER CHROME MOULDING O/S	one	228.00	\$245.00	/
1PC	HEADLAMP O/S	one	2363.65	\$3,900.00	/
1PC	FRONT FENDER O/S	scr/scr	630.25	\$915.00	/
1PC	FRONT FENDER INNER SHIELD O/S	Torn	242.00	\$288.00	/
1SET	FRONT FENDER INNER SHIELD CLIPS O/S	neu		\$50.00	/
1PC	WASHER TANK	De	260.00	\$305.00	/
1PC	FRONT SHOCK ABSORBER O/S	scr/scr	322.75	\$845.00	/
1PC	FRONT KNUCKLE ARM O/S	scr	506.35	\$1,255.00	/
1PC	FRONT WHEEL HUB BEARING O/S	Damaged	300.00	\$650.00	/
1PC	FRONT LOWER ARM O/S	Buc	345.00	\$925.00	/
1PC	FRONT DRIVE SHAFT O/S	11		\$1,650.00	x
1PC	FRONT DOOR O/S	scr/scr	1655.22	\$2,201.00	/
1PC	FRONT DOOR INNER RUBBER O/S	neu	162.00	\$280.00	/
1SET	FRONT DOOR FRAME STICKER O/S	neu		\$60.00	/
1PC	FRONT DOOR OUTER PILLAR O/S	R		\$925.00	x
1PC	REAR DOOR O/S	R		\$1,750.00	x
1PC	ROCKER PANEL GARNISH O/S	scr/torn	725.00	\$900.00	/
1SET	ROCKER PANEL GARNISH CLIPS O/S	neu		\$50.00	/
				\$21,337.00	

S.NETT

1PC	FRONT SPORT RIM O/S	scr/scr		\$1,200.00	600 s/n
1PC	FRONT TYRE O/S	one	12200 702	\$250.00	140 s/n

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REPLACED FRONT PDC SENSOR	\$80.00	50
TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE	\$180.00	120
TO DISMANTLE & REFIX FRONT DOOR MECHANISM	\$120.00	60
TO RESET & DIAGNOSTIC SYSTEM	\$200.00	50
TO SPRAY RUST PROOFING	\$100.00	60

TO CONDUCT WHEEL ALIGNMENT
 LABOUR FOR PANEL BEATING & REPLACED PARTS
 TO PUTTY & SPRAY PAINTING

	\$120.00	80
	\$1,000.00	600
	\$1,800.00	900
TOTAL	\$26,437.00	

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-10007-72
 52
 7-9507-33
 5-N-740
 1-1940
 12187-33
 9749.