

COMFORTDELGRO
ENGINEERING

Our Job Ref No : 305510959
Date 07.04.22

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156


FINALIZATION FORM

To : LKK
Attn : Mr THEVAN
Vehicle Reg No. SHA1672D
Date of Accident : 01.04.22

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: **GAIG** --- **GBG9639M**
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges
 - Total for Part-By-Part Repair Cost**
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% **\$1,300.00**
Final Lumpsum Repair cost
3. Estimated normal period for repairs: 2 working days.
4. We shall treat the above amount as **Correct and Confirmed** if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and
finalized amount

Signature : 
Name : JUMANI
Tel : 62148315
Fax : 65468156

Signature : 
Name : THEVAN
Date : 21/4/22

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	NO		
3. Survey Fees	---	---		
LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Great American
(US)

Date: 01.04.2022
Time: 13:56:58
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305510959
REGN NO : SHA1672D
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 05.07.2018
DATE/TIME IN : 01.04.2022 10:30
ACCIDENT DATE : 01.04.2022

JOB / PARTS DESCRIPTION QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G COVER-RR BUMPER#	1	459.40	20.00	367.52	Kr/Cut
0002 04-01-0104-2533-G MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00	Sc
0003 04-01-0104-2545-G MOULDING-REAR BUMPER LWR	1	155.00	20.00	124.00	XSC
0004 04-01-0101-0111-G BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	hxc
0005 04-01-0104-2544-G BUMPER TOW COVER	1	98.80	20.00	79.04	XSC
0006 09-01-9999-0068-A REVERSE SENSOR ASSY*	1	180.00	2.00-	180.00	XSC
0007 04-01-0104-1150-A PROTECTOR MAT	1	50.00	0.20	50.00	XSC

SUB-TOTAL : 1,179.16

JOB NATURE

0000 PB	PANEL BEATING	400.00	350
0001 SP	SPRAYPAINT CHARGE	300.00	250
0002 L	REMOVE/REFIX REVERSE SENSOR	120.00	30
0003 20-05	REAR FENDER ADV.STICKER RH/LH	200.00	/me