

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

Lonpac Insurance Bhd
 300 Beach Road #17-04/07
 The Concourse
 Singapore 199555
 Tel: 6250 7388
 Fax: 6296 2706

QUOTATION
 DATE : 01.04.2022
 VEH NO : SMR4422R
 MODEL : Toyota Wish
 D O A : 31.03.2022
 YR REF : Own Damage

Attn : Motor Claims Dept

RE : ESTIMATE FOR ACCIDENT REPAIR SMR4422R (TOYOTA WISH)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
1	Front Bonnet Lock <i>BT</i>	1	100.00 ✓
2	Front Bonnet <i>one</i>	1	1,047.80 <i>768.1</i>
3	Front Bonnet Hinges - LH & RH <i>BT</i>	1	140.00 ✓
4	Front Bumper <i>Re</i>	1	636.70 <i>594</i>
5	Front Bumper Reinforcement <i>BT</i>	1	333.60 <i>298.7</i>
6	Front Grille <i>Cut</i>	1	450.70 <i>385.15</i>
7	Front Bumper Sponge <i>CEA</i>	1	118.00 ✓
8	Brace Panel <i>BT</i>	1	105.00 ✓
9	Front Support Panel <i>BT</i>	1	1,585.50 <i>874</i>
10	Head Lamp - LH <i>LR</i>	1	1,060.00 <i>959</i>
11	Head Lamp - RH <i>LR</i>	1	1,060.00 <i>959</i>
12	Air Condenser <i>Cut</i>	1	1,950.00 <i>1355.32</i>
13	Radiator Assy <i>CUT</i>	1	2,290.10 <i>1493.7</i>
14	Radiator Fan Cowling <i>BR</i>	1	290.90 <i>278.6</i>
15	Front Bumper Side Bracket - LH <i>X NN</i>	1	80.00
16	Radiator Side Garnish - LH <i>X NN</i>	1	95.30
17	Top Panel Garnish <i>Cut</i>	1	115.10 ✓
18	Top Panel Garnish Clips <i>one</i>	1 set	30.00 ✓
19	Bonnet Insulator <i>X NN</i>	1	440.40
20	Front Bonnet Emblem <i>one</i>	1	60.60 ✓
21	Front Bumper Lower Grille - RH <i>Re</i>	1	70.40 ✓
22	Fog Lamp Garnish - RH <i>X NN</i>	1	85.10
23	Front Fender - RH <i>X repair</i>	1	1,150.00
Sub Total			13,295.20 <i>8704.67</i>
Add 15%			1,994.28
Total Parts			\$ 15,289.48

-25%: 6528.5

RE: ESTIMATE FOR ACCIDENT REPAIR SMR4422R (TOYOTA WISH)

S/NET ITEMS

1	Front Number Plate	1	\$	30.00	20
2	Front Number Plate Garnish	1	\$	30.00	20
3	Radiator Blade	1	\$	120.00	60
				\$	180.00
Total Parts			\$	15,469.48	

Labour Charge:

1	To knocking & pull out front portion and renew above parts	\$	1,200.00	600	
2	To putty and spray up paint work	\$	800.00	700.	
3	To check wiring system	\$	20.00	✓	
4	To underseal	\$	30.00	✓	
5	To remove air condensor and top up gas	\$	120.00	} 120.	
6	To remove radiator and top up coolant	\$	120.00		
			\$	2,290.00	1470
Grand Total		\$	17,759.48		

GST Will be reflected in the final bills

8098.5

NOTE : -

-20%: 6450

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

5 Days.

4/5

After repair photos

Gmc Qiang
8288-282

4/4/22

Not Authorised.

No excess applicable under section 1

LINK Auto Consultants hence notify the Repairer of the following:	
• To survey before/after spray painting	
• To display damaged part(s) during survey	
• Parts prices are subject to confirmation	
• Third party survey is on a "Without Prejudice" basis	
• No illegal modification(s) is allowed	
• Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company	
Acknowledged by Repairer	
Signature:	
Date:	