

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 02.04.2022

TO : AXA MOTOR CLAIMS DEPTS
VEHICLE NO : SJS6298A
MODEL : TOYOTA ESTIMA
DATE OF ACCIDENT : 01.04.2022
TIME OF ACCIDENT : 18:55HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER	1	\$ 1,425.00	\$ 1,425.00
2	FRONT BUMPER FOGLAMP	2	\$ 545.00	\$ 1,090.00
3	FRONT BUMPER FOGLAMP HOUSING	2	\$ 168.00	\$ 336.00
4	FRONT BUMPER FOG LAMP RING	2	\$ 114.00	\$ 228.00
5	FRONT BUMPER TOWING COVER	2	\$ 35.00	\$ 70.00
6	FRONT BUMPER LOWER GRILLE	1	\$ 495.00	\$ 495.00
7	FRONT BUMPER LOWER GRILLE CHROME	1	\$ 285.00	\$ 285.00
8	FRONT BUMPER SIDE GRILLE GARNISH RH	1	\$ 59.00	\$ 59.00
9	FRONT BUMPER SIDE RETAINER	2	\$ 110.00	\$ 220.00
10	FRONT BUMPER SPONGE	1	\$ 295.00	\$ 295.00
11	FRONT BUMPER REINFORCEMENT	1	\$ 795.00	\$ 795.00
12	FRONT BUMPER WIRE HARNESS	1	\$ 1,209.00	\$ 1,209.00
13	FRONT BUMPER UNDER COVER GARNISH	1	\$ 265.00	\$ 265.00
14	ENGINE SIDE COVER GARNISH LH	1	\$ 232.00	\$ 232.00
15	ENGINE UNDER COVER GARNISH	1	\$ 386.00	\$ 386.00
16	HEADLAMP	2	\$ 1,970.00	\$ 3,940.00
17	FRONT WIPER GARNISH	1	\$ 790.00	\$ 790.00
18	FRONT WIPER SIDE GARNISH	2	\$ 106.00	\$ 212.00
19	FRONT GRILLE	1	\$ 495.00	\$ 495.00
20	FRONT GRILLE LOGO	1	\$ 90.00	\$ 90.00
21	FRONT GRILLE TOP RUBBER GARNISH	1	\$ 68.00	\$ 68.00
22	BONNET	1	\$ 690.00	\$ 690.00
23	BONNET STOPPER	2	\$ 28.00	\$ 56.00
24	BONNET HINGE	2	\$ 175.00	\$ 350.00
25	BONNET LOCK	1	\$ 180.00	\$ 180.00
26	BONNET INSULATOR	1	\$ 398.00	\$ 398.00
27	FRONT SUPPORT PANEL	1	\$ 1,095.00	\$ 1,095.00

TO : AXA MOTOR CLAIMS DEPTS
 VEHICLE NO : SJS6298A
 MODEL : TOYOTA ESTIMA
 DATE OF ACCIDENT : 01.04.2022
 TIME OF ACCIDENT : 18:55HRS

28	FRONT SUPPORT PANEL TOP COVER GARNISH	1	\$ 395.00	\$ 395.00
29	HORN	2	\$ 68.00	\$ 136.00
30	AIR CON CONDENSER SIDE GARNISH	2	\$ 65.80	\$ 131.60
31	AIR CON CONDENSER	1	\$ 1,093.00	\$ 1,093.00
32	AIR CON CONDENSER MOUNTING	4	\$ 28.00	\$ 112.00
33	RADIATOR TOP SUPPORT GARNISH	1	\$ 78.10	\$ 78.10
34	RADIATOR	1	\$ 1,895.00	\$ 1,895.00
35	RADIATOR TOP BRACKET	2	\$ 28.60	\$ 57.20
36	RADIATOR FAN COWLING	1	\$ 687.00	\$ 687.00
37	RADIATOR RUBBER MOUNTING	4	\$ 25.40	\$ 101.60
38	FRONT TEMPERATURE SENSOR	1	\$ 108.50	\$ 108.50
39	FUSE BOX	1	\$ 770.00	\$ 770.00
40	WIPER WASHER TANK	1	\$ 260.00	\$ 260.00
41	RESORNATOR BOX	1	\$ 287.00	\$ 287.00
42	RESORNATOR DUCT	2	\$ 160.00	\$ 320.00

TOTAL PRICE \$ 22,186.00
 LESS 25% \$ 5,546.50
SUB TOTAL PRICE \$ 16,639.50

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE	1	\$ 60.00	\$ 60.00
2	FRONT BUMPER CLIP (SET)	1	\$ 80.00	\$ 80.00
3	ENGINE SIDE COVER GARNISH CLIP (SET)	1	\$ 60.00	\$ 60.00
4	ENGINE UNDER COVER GARNISH CLIP (SET)	1	\$ 80.00	\$ 80.00
5	FRONT WIPER GARNISH CLIP (SET)	1	\$ 50.00	\$ 50.00
6	FRONT GRILLE CLIP (SET)	1	\$ 50.00	\$ 50.00
7	BONNET SEALANT	1	\$ 120.00	\$ 120.00
8	BONNET INSULATOR CLIP (SET)	1	\$ 60.00	\$ 60.00
9	FRONT SUPPORT PANEL SEALANT	1	\$ 120.00	\$ 120.00
10	FRONT SUPPORT PANEL TOP COVER GARNISH	1	\$ 60.00	\$ 60.00
11	FRONT SUPPORT PANEL BOTTOM COVER GARNISH	1	\$ 60.00	\$ 60.00
12	AIR CON CONDENSER SIDE GARNISH CLIP (SET)	1	\$ 40.00	\$ 40.00
13	RADIATOR TOP SUPPORT GARNISH CLIP (SET)	1	\$ 50.00	\$ 50.00
14	FRONT FENDER INNER COWLING CLIP (SET)	1	\$ 80.00	\$ 80.00
15	RADIATOR COOLANT	1	\$ 60.00	\$ 60.00

TOTAL \$ 1,030.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
-----	-----------------	-------	---------------

TO : AXA MOTOR CLAIMS DEPTS
 VEHICLE NO : SJS6298A
 MODEL : TOYOTA ESTIMA
 DATE OF ACCIDENT : 01.04.2022
 TIME OF ACCIDENT : 18:55HRS

1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,800.00	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	
3	Tuff Coat	\$ 250.00	
4	WIRING CHECK	\$ 80.00	
5	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	
6	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	
7	REFOCUS HEADLAMP BEAM	\$ 60.00	
8	FRONT CHASSIS ALIGNMENT	\$ 250.00	
9	RESET ENGINE LIGHT	\$ 350.00	
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	

TOTAL \$ 4,770.00

TOTAL PARTS COST : \$ 17,669.50
 TOTAL LABOUR COST : \$ 4,770.00
 TOTAL REPAIR COST : \$ 22,439.50

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
 PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR

IRENE

HP : 8297 9787