



TO : AXA MOTOR CLAIMS DEPTS  
 VEHICLE NO : SJS6298A  
 MODEL : TOYOTA ESTIMA  
 DATE OF ACCIDENT : 01.04.2022  
 TIME OF ACCIDENT : 18:55HRS

28	FRONT SUPPORT PANEL TOP COVER GARNISH <i>Del'd</i>	1	\$ 395.00	\$ 395.00	← 285
29	HORN <i>could</i>	2	\$ 68.00	\$ 136.00	-
30	AIR CON CONDENSER SIDE GARNISH <i>Del'd</i>	2	\$ 65.80	\$ <del>131.60</del>	82
31	AIR CON CONDENSER <i>Dented</i>	1	\$ 1,093.00	\$ 1,093.00	✓
32	AIR CON CONDENSER MOUNTING <i>new</i>	4	\$ 28.00	\$ 112.00	x
33	RADIATOR TOP SUPPORT GARNISH <i>could</i>	1	\$ 78.10	\$ 78.10	✓
34	RADIATOR <i>Dented</i>	1	\$ 1,895.00	\$ <del>1,895.00</del>	→ 1730
35	RADIATOR TOP BRACKET <i>Set</i>	2	\$ 28.60	\$ 57.20	-
36	RADIATOR FAN COWLING <i>new</i>	1	\$ 687.00	\$ 687.00	+
37	RADIATOR RUBBER MOUNTING <i>new</i>	4	\$ 25.40	\$ 101.60	x
38	FRONT TEMPERATURE SENSOR <i>new</i>	1	\$ 108.50	\$ 108.50	+
39	FUSE BOX <i>new</i>	1	\$ 770.00	\$ 770.00	x
40	WIPER WASHER TANK <i>new</i>	1	\$ 260.00	\$ 260.00	+
41	RESORNATOR BOX <i>got</i>	1	\$ 287.00	\$ 287.00	+
42	RESORNATOR DUCT <i>new</i>	2	\$ 160.00	\$ 320.00	+

1173030 TOTAL PRICE \$ 22,186.00  
 879772 LESS 25% \$ 5,546.50  
**SUB TOTAL PRICE \$ 16,639.50**

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE <i>Dented</i>	1	\$ 60.00	\$ 60.00	30
2	FRONT BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ <del>80.00</del>	30
3	ENGINE SIDE COVER GARNISH CLIP (SET) <i>2</i>	1	\$ 60.00	\$ 60.00	+
4	ENGINE UNDER COVER GARNISH CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
5	FRONT WIPER GARNISH CLIP (SET)	1	\$ 50.00	\$ 50.00	+
6	FRONT GRILLE CLIP (SET) <i>new</i>	1	\$ 50.00	\$ <del>50.00</del>	20
7	BONNET SEALANT <i>got</i>	1	\$ 120.00	\$ 120.00	+
8	BONNET INSULATOR CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	+
9	FRONT SUPPORT PANEL SEALANT <i>new</i>	1	\$ 120.00	\$ 120.00	x
10	FRONT SUPPORT PANEL TOP COVER GARNISH <i>new</i>	1	\$ 60.00	\$ <del>60.00</del>	20
11	FRONT SUPPORT PANEL BOTTOM COVER GARNISH <i>new</i>	1	\$ 60.00	\$ 60.00	2. 160
12	AIR CON CONDENSER SIDE GARNISH CLIP (SET) <i>new</i>	1	\$ 40.00	\$ <del>40.00</del>	10
13	RADIATOR TOP SUPPORT GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ <del>50.00</del>	10
14	FRONT FENDER INNER COWLING CLIP (SET)	1	\$ 80.00	\$ 80.00	+
15	RADIATOR COOLANT <i>new</i>	1	\$ 60.00	\$ <del>60.00</del>	40

**TOTAL \$ 1,030.00**

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING**

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
-----	-----------------	-------	---------------

TO : AXA MOTOR CLAIMS DEPTS  
 VEHICLE NO : SJS6298A  
 MODEL : TOYOTA ESTIMA  
 DATE OF ACCIDENT : 01.04.2022  
 TIME OF ACCIDENT : 18:55HRS

1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,800.00	900
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	800
3	Tuff Coat	\$ 250.00	80
4	WIRING CHECK	\$ 80.00	30
5	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	60
6	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	60
7	REFOCUS HEADLAMP BEAM	\$ 60.00	X
8	FRONT CHASSIS ALIGNMENT	\$ 250.00	X
9	RESET ENGINE LIGHT	\$ 350.00	X
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

1930

**TOTAL \$ 4,770.00**

TOTAL PARTS COST : \$ 17,669.50  
 TOTAL LABOUR COST : \$ 4,770.00  
 TOTAL REPAIR COST : \$ 22,439.50

Adrian G  
 1/2 06/04/22.  
 06 Days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.  
 PARTS PRICES ARE SUBJECT TO CHANGES.

total: 10887.72  
 1/2: 871c

YOURS FAITHFULLY,

**IRENE**

SERVICE ADVISOR  
 IRENE  
 HP : 8297 9787

8.7k

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: