



UCB Engineering Pte Ltd

Business Reg. No. 199501338G.

Our ref: 220401.WW(PC3737H))

04 April 2022

Lonpac Insurance Bhd
300 Beach Road
Singapore 199555

without Prejudice
email: mt_claim@lonpac.com

Attention : Motor Claims Department

Dear Sirs

ACCIDENT INVOLVING PC 3737 H AND GBK 398 X 21/01/2022 AT CARPARK OF NORTH VISTA PRIMARY SCHOOL

We refer to the above matter.

Our client's vehicle, PC 3737 H was damages by your insured in an accident on 21/01/2022.

Our client proposed to file for third party claim for the losses incurred. Enclosed herewith please find a copy of the quotation from our workshop as well as our client's GIA report for your kind attention.

Please arrange for your surveyor to liaise with us for an inspection on our client's vehicle at your earliest convenient. Kindly contact Madam Ah Siang at 62681281, 91773084 or Mr. Tan at 97381908.

Yours faithfully

Tan Tiong Chin

Encs GIA report for PC 3737 H
Quotation



UCB Engineering Pte Ltd

Business Reg. No. 199501338G

Our ref: 220401.WW(PC3737H)

Your ref :

02 April 2022

Wei Wei Transportation
Blk 536 Bedok North Street 3
#06-872
Singapore 460536

QUOTATION
without Prejudice

Dear Sir,

COST OF REPAIR FOR PC 3737 H

<u>QTY</u>	<u>DESCRIPTIONS</u>	<u>PRICE</u> <u>S\$</u>
1 pc	Front panel	2,450.00
1 pc	Front windscreen glass	1,850.00
1 pc	ERP Bracket	26.00
6 tubes	Sealant @\$40/-	240.00
1pc	Windscreen weatherstrip	580.00
1 pc	Front grille	650.00
1 pc	Headlamp	580.00
	Labour charges to remove & replace front windscreen	650.00
	Side window glass	
	Labour charges for dismantle & assemble dashboard	550.00
	Labour charges for remove & replace the above	1,800.00
	damaged parts, checking alignment	
	Wiring Charges	60.00
	To putty & spray painting onto affected areas	1,050.00
	TOTAL	10,486.00

(Sgd: Ten Thousand Four hundred And Eighty-Six Only)

Yours faithfully,
Tan Tiong Chia