



# UCB Engineering Pte Ltd

Business Reg. No. 199501338G.

Our ref: 220401.WW(PC3737H)  
Your ref :

02 April 2022

Wei Wei Transportation  
Blk 536 Bedok North Street 3  
#06-872  
Singapore 460536

QUOTATION  
without Prejudice

Dear Sir,

## COST OF REPAIR FOR PC 3737 H

QTY	DESCRIPTIONS	PRICE S\$
1 pc	Front panel	2,450.00 <i>bt</i>
1 pc	Front windscreen glass	1,850.00 <i>x nn</i>
1 pc	ERP Bracket	26.00 <i>x nn</i>
6 tubes	Sealant @ \$40/-	240.00 <i>x nn</i>
1 pc	Windscreen weatherstrip	580.00 <i>alc</i>
1 pc	Front grille	650.00 <i>alc</i>
1 pc	Headlamp	580.00 <i>7 Cua</i>
	Labour charges to remove & replace front windscreen	650.00 <i>200</i>
	Side window glass	
	Labour charges for dismantle & assemble dashboard	550.00 <i>x nn</i>
	Labour charges for remove & replace the above damaged parts, checking alignment <i>\$350/day</i>	1,800.00 <i>1400</i>
	Wiring Charges	60.00 <i>30</i>
	To putty & spray painting onto affected areas	1,050.00 <i>900</i>
	TOTAL	10,486.00

(Sgd: Ten Thousand Four hundred And Eighty-Six Only)

Yours faithfully,  
Tan Tiong Chia

*Tan Tiong Chia 97445749 / 62563561*  
*WP 4/4/22 @ 320 pm*  
*1/5 Resurvey after repair*  
*06 days to 7 days*  
*tanfiah@thkauto.com*  
*To check it do p/p 1 to call w/s.*

*Part - 4500*  
*25% - 3375*  
*Labour - 2530*  
*5905*  
*10% - 590.5*  
*7 days #*

- Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: