



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref: CS/ASM22003086/Uvy3e2

8 SHENTON WAY #24-01 AXA TOWER  
SINGAPORE 068811

Date: 04/05/2022

ATTN: ANG YVONNE

Code: ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SLU 786M	<b>Veh. Inspected</b>	SJN 2948K
<b>Policy No.</b>	GA588321	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	S2M03XGH	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	ANG YVONNE	<b>Assign Date</b>	04/04/2022

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	TOYOTA PICNIC (A)	<b>c.c</b>	1998
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2009
<b>Chassis No.</b>	JTEGH23B300026393	<b>Colour</b>	SILVER
<b>Odometer</b>	212289 KM	<b>Steering</b>	AFFECTED
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	205/60 R16	BRIDGESTONE	3 mm
<b>L/H Front Tyre</b>	205/60 R16	BRIDGESTONE	3 mm
<b>R/H Rear Tyre</b>	205/60 R16	BRIDGESTONE	5 mm
<b>L/H Rear Tyre</b>	205/60 R16	BRIDGESTONE	5 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	31/03/2022	<b>Inspection Date</b>	05/04/2022
<b>Survey held at</b>	IMPERIUM AUTOMOTIVE 25 KAKI BUKIT ROAD 4 #01-49 SYNERGY @ KB SINGAPORE 417800		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**