

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0219/2022/JT
DATE : 23-Mar-22
WIP : 16445

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 25/3/22

YOUR INSURED VEH NO : SGX 6556 P

HL ASSURANCE Pte Ltd

11 KEPPEL ROAD

#11-01 ABI PLAZA

SINGAPORE 089057

Attn: Motor Claims Dept

Tel: 65 6922 6017 - Fax: 65 6224 1923

Hi Adrian,

4 days - ok - Jy - 1 Jun 22

OWNER'S NAME : MR CHOY RUI CHENG
ADDRESS : BLK 265D PUNGGOL WAY
#03-354
SINGAPORE 824265
TELEPHONE : HP +65 8121158
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 7210108895
VEHICLE NO : SML 2384 L
MODEL CODE : AUDI A3 SEDAN 1.5 TFSI
MODEL YEAR : 09/09/2021
ENGINE NO : DFY 295647
CHASSIS NO : WAUZZZGY7NA007054
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 20-Mar-22
PLACE OF ACCIDENT : FUNAN MALL CAR PARK B4 LOT-147

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SML 2384 L

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,100.00	\$ 700.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$	2,000.00	\$ 1,400.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$	5,122.00	\$ 2,772.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 2384 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 1,677.00	
2	FRONT BUMPER FIXING PARTS	1	\$ 290.00	
3	FRONT BUMPER CLOSING ELEMENT - RH	1	\$ 130.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$ 265.00	
5	FRONT BUMPER AIR GUIDE - RH	1	\$ 67.00	
6	FRONT BUMPER TRIM COVER - RH	1	\$ 104.00	
7	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 171.00	
8	FRONT BUMPER AIR GUIDE SUPPORT - RH	1	\$ 43.00	
9	FRONT BUMPER GUIDE SECTION - RH	1	\$ 54.00	
10	FRONT BUMPER TOP COVER	1	\$ 93.00	
11	CAUTION STICKER	1	\$ 16.00	
12	AIR COND STICKER	1	\$ 9.00	
13	FRONT FENDER - RH	1	\$ 1,241.00	
14	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 32.00	
15	FRONT FENDER POP RIVET	3	\$ 12.00	
16	FRONT FENDER BRACE - RH	1	\$ 98.00	
17	FRONT FENDER BRACKET - RH	1	\$ 46.00	
18	FRONT FENDER BRACKET END - RH	1	\$ 35.00	
19	FRONT WHEEL HOUSING LINER - RH	1	\$ 183.00	
20	FRONT WHEEL HOUSING LINER CLOSING ELEMENT - RH	1	\$ 22.00	
SUB TOTAL SPARE PARTS		:	\$ 4,588.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 2384 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	HEADLIGHT - RH	1	\$ 4,084.00	
22	LIFT CYLINDER - RH	1	\$ 211.00	
23	LIFT CYLINDER HOSE	1	\$ 108.00	
24	FRONT PARKING AID SENSOR SIDE	1	TBC	
25	FRONT PARKING AID SENSOR SEAL RING	4	\$ 32.00	
26	SUNDRIES		\$ 300.00	
TOTAL SPARE PARTS		:	\$ 9,323.00	\$ -
TOTAL LABOUR CHARGES		:	\$ 5,122.00	\$ 2,772.00
GRAND TOTAL		:	\$ 14,445.00	\$ 2,772.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-25/05/22