

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	onale Des Experts Er	n Automo	obile CS3/A	SM21011090
	AXA INSURANCE PTE LTD			Ref:	-000/A0M21	
	8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811			Date:	20/40/2024	04/04/2022
				Code:	ASM	
۱.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHA 2902J	Veh. Inspected	k	SLQ 5025P	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	S1M03KYI	Excess (\$)		0.00	
	Assign From	CHEN XINYOU	Assign Date		29/19/2021	04/04/2022
2.	Vehicle Particulars & Condition					
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
•			ions of Tyres			
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
•	Description of Damages					
j.		Compare	al Information			
).	Accident Date	26/10/2021	Inspection Dat	ή		
			•			
	Repairer	1 Kaki Bukit Avenue 6 #01-87 Autobay@Kaki Bukit Z-ONE AUTOMOTIVE PTE LTD				
ia.	Remarks					
-ui	B) THE REPAIR E THE REPAIRER V	NSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. PAIRER WAS TOLD TO PREPARE THE ESTIMATE. OSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				