

ASS. REC. BY:

REF:

ASM/ 22003112/KgY3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NII / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 / GIA & EIA not ready

13/4 / 11pm @ 34001 Concur (Red 63626-90, 522)

11/05/22 @ 3.10pm revised to Chan Kian Chuan via Smart Claims.

Date/Time, File Pass to?

1) 11/5 AMESH

Date/Time, File Return to?

2)

☐

: Prell. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$

Smart Claims - TP

3400

RIVERVIEW AUTO SERVICES PTE LTD

10 ANG MO KIO INDUSTRIAL PARK 2A
#04-07/#04-16 AMK AUTOPOINT
SINGAPORE 568047

Tel: 6481 2025 / 6481 5797 Fax: 6481 8715

Email: service@riverviewauto.com.sg

Website: www.riverviewauto.com.sg

Co.Reg No: 200800062E GST.Reg No: 200800062E

Lump Sum
less 20%

Not Withheld
11 Lm \$3400k
Resurvey After Paint
6 days

SJS88572
Parts

Toyota Vios

List Price \$
Toyota less 25%

Bootlid	658.70	R 878.10	✓
Bootlid 'Vios' emblem		M 45	✓
Bootlid Toyota Badge		M 48	✓
Bootlid 'E' emblem		M 41	✓
Bootlid no plate lamp garnish		M 122	✓
Bootlid hinges x 2pc		N @ \$98 x 2pc = 196	X
Bootlid inner lock		M 124.10	✓
Rear Bumper	488.20	M 580.10	✓
Rear Bumper reflector x 2pc		015 cm @ \$81.90 x 2pc = 163.80	✓
Rear Bumper side retainer x 2pc		D17 @ \$44.20 x 2pc = 88.40	✓
taillamp x 2pc	0342.00	CM @ \$378.10 x 2pc = 756.20	✓
taillamp gasket x 2pc		M @ \$34.50 x 2pc = 69	✓
end panel lock catch		N 40	X
Boot weatherstrip		M 176.30	50% in
Rear end panel top garnish		M 123	✓
Rear end panel	588.30	M 787.90	✓
spare tyre top cardboard		M 278.90	X
spare tyre panel		Repair	

Special nett items

nett price \$

Rear license plate with holder	M 50	45% in
Reverse parking sensors	M 250	200% in
Rear Bumper clips (1 set)	M 40	✓
Rear end panel sealant	M 180	30% in

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Pg 1

RIVERVIEW AUTO SERVICES PTE LTD

10 ANG MO KIO INDUSTRIAL PARK 2A

#04-07/#04-16 AMK AUTOPOINT

SINGAPORE 568047

Tel : 6481 2025 / 6481 5797 Fax : 6481 8715

Email : service@riverviewauto.com.sg

Website : www.riverviewauto.com.sg

Co.Reg No: 200800062E GST.Reg No: 200800062E

Lump Sum
less 20%

SJS 88572

Toyota Vios

Labour charges

- 1) To Renew the Damaged parts. To cut & weld the Rear end panel. To panel beat the spare tyre panel and repair the accident Area. \$1200 600
- 2) To assemble Reverse parking sensors & check for proper functions! \$80 50
- 3) To spray paint Bootlid, Rear Bumper, Rear end panel & spare tyre panel. \$1200 800
- 4) To carry out anti-rust treatment at the affected panels of the accident Area. \$120 60

KK Auto Consultants hence notify
the Repairer of the following:

- To display damaged part(s) during survey
- To rectify defective spray painting
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be removed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Pa 2