

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance
(Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jacqueline Tan

Date: 06 Apr 2022

Preliminary Advice

Insured : YQ3810Z
Vehicle No
TP Vehicle : GBH7445M Accident Date : 01/04/2022
No
Make : NISSAN NV350 Assignment Date : 05/04/2022
Date of : 05/04/2022 Est. Duration of : 12
Inspection Repair
Inspection At : AUTOLUTION INDUSTRIAL PTE LTD (UBI)
19 UBI ROAD 4
SINGAPORE 408623

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,197.12
Revised Amount	:S\$	11,377.84
Check Items (Estimated)	:S\$	4,314.90
Total	:S\$	15,692.74

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$

Salvage Value :S\$

Margin for Repair :S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.