

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

| PRE-REPAIR INSPECTION REPORT | | | | | | |
|------------------------------|---|---|------------------|------------|-------------------------|--|
| | AXA INSURANCE | PTE LTD | Ī | Ref: | CS3/ASM22003118/Tvy3e2 | |
| | 8 SHENTON WAY SINGAPORE 0688 | 1 | Date: | 11/05/2022 | | |
| | ATTN : KOH JANIC | CE | (| Code: | ASM | |
| 1. | Policy Particulars :- (THIRD PARTY CLAIM) | | | | | |
| | Insured Veh. | SNE 150H | Veh. Inspected | | FBC 2408E | |
| | Policy No. | | Coverage (\$) | | 0.00 | |
| | Claim No. | S2M03XGA | Excess (\$) | | 0.00 | |
| | Assign From | KOH JANICE | Assign Date | | 05/04/2022 | |
| 2. | 2. Vehicle Particulars & Condition | | | | | |
| | Make & Model | HONDA ANF 125MSS A | c.c | | 125 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2008 | |
| | Chassis No. | NF125MM5000747 | Colour | | RED | |
| | Odometer | - | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | NIL | |
| | General | GOOD | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 70/90R17 | DUNLOP | | 5 mm | |
| | L/H Front Tyre | | | | mm | |
| | R/H Rear Tyre | 80/90R17 | DUNLOP | | 5 mm | |
| | L/H Rear Tyre | | | | mm | |
| 4. | Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT, REAR PORTION AND N/S BODY. | | | | | |
| 5. General Information | | | | | | |
| | Accident Date | 29/03/2022 | Inspect Date / T | ime | 07/04/2022 (10:51 AM) | |
| | Survey held at | SS MOTORING | | | | |
| | | 1084 SERANGOON ROAD SINGAPORE 328186 | | | | |
| 5a. | Remarks | | | | | |
| | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$2,500 | | | | | |
| 5b. | Estimate Days of Repair | | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days | | | | | |

Report Ref No. CS3/ASM22003118/Tvy3e2

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser