

Our Job Ref No : 305510955

Date : 09.04.2022

COMFORTDELGRO
ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

FINALIZATION FORM

To : LKK

Fax :

Attn : THEVAN

Vehicle Reg No. : SH8773H

31.03.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

Z The repair job shall bill to: CHINA YP6032M

2. The finalized amount shall be:

(a) Spare Parts after List discount \$385.12

(b) Labour Charges \$630.00

Total for Part-By-Part Repair Cost \$1,015.12

(c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: _____
Final Lumpsum Repair cost _____

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : _____

Signature : _____

Name : CHIANG

Name : Thevan

Tel : 62148314

Date : 22/4/22

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 06.04.2022

Time: 11:05:13

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305510955
REGN NO : SH 8773H
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 25.02.2021
DATE/TIME IN : 31.03.2022 15:55
ACCIDENT DATE : 31.03.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G COVER-RR BUMPER# 1 459.40 20.00 367.52

0002 04-01-0101-0111-G BUMPER COVER CLIP REAR 10 L 22.00 20.00 17.60

SUB-TOTAL : 385.12

JOB NATURE

0000 PB PANEL BEATING SH8773/TP 350.00

0001 SP SPRAYPAINT CHARGE 250.00

0002 20-22 REMOVE/REFIX REVERSE SENSOR 30.00

SUB-TOTAL : 630.00

TOTAL : 1,015.12

MVA NAME & SIGNATURE

DATE :

SURVEYOR NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

08/11/2021

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SH8773H

31.03.2022

MAKE REG 25.02.2021

CHIANG/CHINA

MODEL IONIQ G3

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER		\$459.40
1	REAR BUMPER SIDE BRACKET RH		\$55.80
1	REAR BUMPER CENTRE MOULDING		\$451.25
10	REAR BUMPER CLIPS	\$2.20	\$22.00
	SUB TOTAL		\$988.45
	20.00%		\$197.69
	DISCOUNTED TOTAL		\$790.76
1	REAR REVERSE SENSOR		\$180.00
1	BOOTLID COMFORT & TEL NUMBER		\$55.00
			\$235.00
	Labour Charge		
	Panel Beating		\$450.00
	Spray Painting Charge	250	\$600.00
	Remove/refix Reverse sensor		\$60.00
	TOTAL LABOUR		\$1,110.00
	ESTIMATE TOTAL		\$2,135.76
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

car
X SUC
X SUC
X SUC
X SUC

X SUC
X SUC
X SUC

350
250
30

Thuan
82235769
1/11/22 1648
P/P repair 3 days

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: