

ASS. REC. BY:

Thevan

REF:

Ntac NS/INC22003120/Vqc

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. **MT/1167987-003**

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: **SHD65656** Yr Regn: **20/12/19**

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **toyota prius hybrid** c.c **1798**Colour **blue** A/C: Insured / Std / NI / NASp. Reading **247883** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **3TDK3Fu303096614**Gen. Cond: **Good** / Fair / Poor / BurntSteering: **In order** / Jammed / Leaked / Burnt orBrake: **In order** / Jammed / Leaked / Burnt orModi: **Nil** / S(Rim) / STD A/Rim orTyre Size: F: **195/65R15**R: **195/65R15**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **westlake**

Front

Rear

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 11/4/22 D.O.I. 11/4/22 1630Survey held at **CDGE**Des. of Damages: Frt / **Rear** / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Thevan finalised LS \$3200, 4 days. (Red \$1437 45, 31%)

Date/Time, File Pass to?

☐

: Prel. Report

1) 30/05 Typist

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format : TPLump Sum **L.B.L. (\$ 3200)**Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

1.04.2022

CHIANG/ NTUC

VEHICLE NO SHD6565G

MAKE REG 20.02.019

MODEL TOYOTA PRIUS G4

Qty	Parts Description/ Labour	Unit Price	Amount
			\$503.04
1	REAR BUMPER		\$112.70
1	REAR BUMPER SIDE RETAINER LH		\$992.04
1	REAR FENDER LH		\$189.60
1	REAR WHEEL COVER LH		\$22.00
10	REAR BUMPER CLIPS	\$2.20	\$1,570.55
1	REAR LH WHEEL RIM		\$3,389.93
	SUB TOTAL		\$847.48
	25.00% DISCOUNTED TOTAL		\$2,542.45
			\$25.00
1	PETROL STICKER		\$80.00
1	REAR DOOR COMFORT APP		\$105.00
	Labour Charge		\$950.00
	Panel Beating		\$800.00
	Spray Painting Charge		\$90.00
	Remove/Refix Upholstery rear		\$90.00
	Tuff Kote		\$60.00
	Check Lighting		\$1,990.00
	TOTAL LABOUR		
	ESTIMATE TOTAL		\$4,637.45

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thuan 82235769

1/4/22 1630

L/S repair 4 days up

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 01.04.2022 14:18

Page :

Team: ARC Repair TP(CLSO)

Sales Order:

305511090

COMFORT TRANSPORTATION PTE LTD
7010045
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755

SHD6565G

TOYOTA

PRIUS HYBRID(G4A 01.04.2022 11

20.12.2019

JTDKB3FU303090614

Accident Date: 01.04.2022
NATURE: 3P 01.04.2022

S/NO	LABOR CODE	DESCRIPTION
------	------------	-------------

SHD6565G

CHIANG

SHD6565G