



# 發 福 摩 哆 車 房 HUAT HOCK MOTOR WORKSHOP

BLOCK 3012, BEDOK NORTH AVE 4, #01-2054.  
BEDOK INDUSTRIAL PARK E, SINGAPORE 489973  
Tel / Fax: 6445 2934 Hp: 8161 6988  
BUSINESS REG NO. 375654/00C

Vehicle No: <u>SBA 1231 P.</u>	Accident Date:
Mileage:	Make / Model: <u>Honda / Shuttle</u>
	CHASSIS: <u>GK8-210060J</u>
Date:	Fax No.: <u>64452934</u>

Items			
1 RH Front Door / BNC		899.5	948.30
2 RH Front Door weatherstrip X			13.20
3 RH Front Door outer glass moulding X	} NN		45.90
4 RH Front Door Glass Guide X			40.70
5 RH Front Door Black Tape Front	} MC	30	50.40
6 RH Front Door Black Tape Rear		30	50.40
7 RH Front Door inner Trim Board X	} NN		556.90
8 RH Front Door inner Trim Board clip X			
9 RH Front Fender Repair X			517.60
10 RH Front Fender inner shield X	} NN		148.30
11 RH Front Fender inner shield clip X			38.00
12 RH Front Tyre / Cat.		135	180.00
13 RH Front Rim X NN			382.20
14 RH Front Tyre Cover / GCR		50(SN)	210.90
15 RH Front shock absorber X	} NN		464.60
16 RH Front lower Arm X			293.30
17 RH Front wheel bearing / BT		✓	159.70
18 RH Front Knuckle Arm X	} NN		328.90
19 RH Front Drive shaft X			1664.30
20 RH Front Anti-Roll bar link X			109.80
21 RH side slip A / Cat.		✓	358.20
			1612.4
		-20%	1289.92



發 福 摩 哆 車 房  
**HUAT HOCK MOTOR WORKSHOP**

BLOCK 3012, BEDOK NORTH AVE 4, #01-2054,  
 BEDOK INDUSTRIAL PARK E, SINGAPORE 489978  
 Tel / Fax: 6445 2934 Hp: 8161 6988  
 BUSINESS REG NO 375654/00C

SBA 1231P.

Labour to remove & replace damage parts Including Realign & Repositioning of replace parts	# 900 <del>350</del> 300
Spray painting materials to spray or replace worn parts and affected necessary parts.	# 900 800
Painting to facilitate works.	# 80 X 11
Transfer front door component	# 150 60.
Under-carriage repair works, Remove & fix up Front Absorber, lower ARM, Knuckle Arm, Shaft & etc.	# 250 150.
To carry out Anti-rust treatment.	# 80 50

1360

Good Q. of

4/5  
 5/4/22  
 After repair photos

2699.92

-20%: 2150

Est to Repair 5 days  
 4

**LK Auto Consultants** hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary (if any) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

# Hock Wah Motor Workshop PTE LTD

Blk 3011 Bedok North Ave4  
#01-2008/2010/2012/2014 Singapore 489977

Phone Number: 6441 5655

Fax Number: 64415355

Customer:

Company:

License No:

Odometer:

**SMH3676J**

Date:

4/5/2022 9:54:58 AM

VIN

Technician:

Order No.:

## VEHICLE ALIGNMENT REPORT

TOYOTA, COROLLA ALTIS(Custom), 13-17,

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	-----	4.2°	5.7°	-----
		Right	-----	4.2°	5.7°	-----
	Camber	Left	0.0°	-0.9°	0.6°	-0.8°
		Right	-0.8°	-0.9°	0.6°	-1.3.2°
	Toe	Left	-63.7	-----	-----	0.3
		Right	61.4	-----	-----	-1.1
Total		-2.3	-0.5	1.7	-0.8	
Rear	Camber	Left	-1.5°	-1.4°	-0.4°	-1.5°
		Right	-1.8°	-1.4°	-0.4°	-1.8°
	Toe	Left	1.6	0.0mm	1.7mm	1.6
		Right	-4.6	0.0mm	1.7mm	-4.7
		Total	-3.0	0.0	3.5	-3.1
	Thrust Angle			-0.5°	-----	-----
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
Steering Wheel	Left		-----	11.3°	11.3°	-----
	Right		-----	11.3°	11.3°	-----
Steering Knuckle Angle	Left		-----	-----	-----	-----
	Right		-----	-----	-----	-----
Steering Knuckle Out On Turns	Left		-----	-----	-----	-----
	Right		-----	-----	-----	-----
Steering Knuckle Maximum Turns	Left		-----	-----	-----	-----
	Right		-----	-----	-----	-----
Steering Knuckle Curve Change	Left		-----	-----	-----	-----
	Right		-----	-----	-----	-----
Steering Knuckle Back	Front		0.1"	-----	-----	-0.6"
	Rear		-0.7"	-----	-----	-1.2"
Steering Knuckle Track Width Diff.			0.2"	-----	-----	1.9"
Steering Knuckle Wheel Base Diff.			0.8"	-----	-----	0.7"
Steering Knuckle Front Ride Height	Left		-----	-----	-----	-----
	Right		-----	-----	-----	-----
Steering Knuckle Rear Ride Height	Left		-----	-----	-----	-----
	Right		-----	-----	-----	-----
Steering Knuckle Toe Angle						