

REPAIR DETAIL S

COMFORTDELGRO
ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Luyang Drive Singapore 508060
Fax 6546 8156

Our Job Ref No : 305511398
Date : 11.04.22

FINALIZATION FORM

To : LKK

Fax :

Attn : THEVAN

Vehicle Reg No. : SHA 896G

Date of Accident : 03.04.22

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: EQ INS --- SMQ1428A
2. The finalized amount shall be:
 - (a) Spare Parts after List discount _____
 - (b) Labour Charges (include advertisement stickers etc, if any) _____
 - Total for Part-By-Part Repair Cost** _____
 - (c.) Lumpsum Repair (if applicable) _____
 - Total for Lumpsum repair cost after Less: 20% \$1,450.00
 - Final Lumpsum Repair cost** \$1,450.00
3. Estimated normal period for repairs: 3 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : [Signature]
Name : LIM T S
Tel : 62148398
Fax : 65468156

Signature : [Signature]
Name : THEVAN
Date : 21/4/22

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	\$7.49 /\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

REPAIR DETAILS**Reference**

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 05 Apr 2022)

Parts: 192 **HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)**

Labour: Repairer's **(Price-denominated Standard List)**

Print Code: **ComfortDelGro Engineering Pte Ltd/SHA896G/05/04/2022 07:21**

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	20.00	0.00	*459.40 FLXr
2	1		*REAR BUMPER CLIPS	20.00	0.00	*2.20 FLXne
3	1		*REAR BUMPER CENTER MOULDING	20.00	0.00	*451.25 FLXSc
4	1		*REAR BUMPER SIDE RETAINER LH	20.00	0.00	*55.80 FLne
5	1		*REAR WHEEL CAP LH	20.00	0.00	*346.40 FLSc
6	1		*REAR FENDER (PETROL ONLY) LH	0.00	0.00	*40.00 Fne
7	2		*REAR FENDER ADVERTISEMENTS STICKER RHLH	0.00	0.00	*200.00 Fnp
8	1		*REAR BUMPER MAT	0.00	0.00	*50.00 FXSc

F=Franchise part, L=ListItemDisc.

Sub Total (\$)	1,605.05
- List Item Discount on L Items (\$)	263.01
Total Parts (\$)	1,342.04

ComfortDelGro Engineering Pte Ltd/SHA896G/05/04/2022 07:21. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

(08)

AS

FI

E

S

4/5/22, 7:22 AM

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Repairer Estimates

Mr. Tan Seng

Estimates on Labour

No Particulars

Labour Items		Lab.Type	Amount
1	PANEL BEATING - REAR FENDER ARCH LH	New	800.00 700
2	SPRAY PAINTING	New	600.00 500
3	R/I REVERSE SENSORS	New	120.00 30
Gross Labour Cost (\$\$)			1,520.00

ComfortDelGro Engineering Pte Ltd/SHA896G/05/04/2022 07:21. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Thuan

82235769

6/4/22 1630

LPS repair 3 days swp

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: